

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0046/2023
DATE : 02-FEB-2023

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE S(079909)
TEL : 6389 6111
FAX : 6222 1033

OWNER'S NAME : RAJ KUMAR S/O SINATHAMBY
ADDRESS : APT BLK 325B SUMANG WALK
#06-955
S(822325)
TELEPHONE NO : 90147035

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPCSNWD025132200 CHINA TAIPIN
VEHICLE NO : SNG9411K
MODEL CODE : GT7CKBL
MODEL/YEAR : IMPREZA 5D 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20CE55875
CHASSIS NO : JF1GT7KL5KG065080
MILEAGE : 1 KM
DATE IN : 02/02/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 02/02/2023

Print Date : 03/02/2023
Print Time : 09:57:30

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SNG9411K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
------	----------	---------------	-------------------	---------------------------

1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST CHINA TAIPING-SLW4905A		
---	---------	---	--	--

2	ZZ/001	DOA:28/JAN/2023 TIME:1200 HRS LOCATION:326 SUMANG WALK,S(821313)		
---	--------	--	--	--

3	ZZ/002	REPLACE FRONT RH DOOR, REAR RH DOOR, RH FENDER AND RH SIDE SKIRT	2100.00	1800
---	--------	---	---------	------

4	ZZ/003	RESPRAY RH FENDER, FRT RH DOOR, REAR RH DOOR AND RH SIDE SKIRT	2400.00	1820
---	--------	---	---------	------

5	ZZ/004	TRANSFER FRONT RH DOOR MECHANISM	200.00	150
---	--------	----------------------------------	--------	-----

6	ZZ/005	TRANSFER REAR RH DOOR MECHANISM	200.00	150
---	--------	---------------------------------	--------	-----

7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	50
---	--------	-------------------------------	--------	----

8	ZZ/007	FAULT DIAGNOSTIC (RESET)	280.00	
---	--------	--------------------------	--------	--

9	ZZ/008	SUNDRIES	100.00	20
---	--------	----------	--------	----

TOTAL LABOUR CHARGES

5380.00

Suppl - 1380

TOTAL - 5650

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNG9411K

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	FENDER F RH <i>replv bt</i> ✓	57120FL0209P	222.00 ✓			
2	PNL COMPL DR F RH <i>turn</i> ✓	60009FL0409P	920.00 ✓			ORDER TCS
3	HINGE ASSY DR F URH <i>x bt</i> ✓	60079FL000	41.40 ✓			
4	HINGE ASSY DR F LRH <i>bt</i> ✓	60079FL020	41.40 ✓			
5	PNL COMPL DR R WRH <i>bt</i> ✓	60409FL0409P	888.00 ✓			
6	TAPE DR SASH F F RH <i>n</i> ✓	90422FL000	11.10 ✓			
7	TAPE DR SASH F M RH <i>n</i> ✓	90422FL020	11.10 ✓			
8	TAPE DR SASH R M WRH <i>n</i> ✓	90422FL040	7.40 ✓			
9	CLIP PAD DR(40038) <i>n</i> ✓	909130051	4.20 ✓			
10	CLIP SD SKIRT BLACK <i>n</i> ✓	909140055	15.00 ✓			
11	SD SPOILER RH <i>replv de</i> ✓	96051FL000NN	647.50 ✓			
SUB TOTAL			2853.50			
LESS DISCOUNT (NETT-20 %)			569.10	0.00	0.00	0.00
GRAND TOTAL			2284.40	0.00	0.00	0.00
OVERALL TOTAL			2247.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SNG9411K

TOTAL LABOUR CHARGES	5380.00
TOTAL SPARE PARTS CHARGES	2247.28
GRAND TOTAL	7627.28 *

5650.00
2282.80
7932.80

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Plate - Hp 90010068
08/02/23 @ 1400
5 days + 2 = 7 days
Resy before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE LABOUR CHARGES FOR ACCIDENT VEHICLE REG.NO SNG9411K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYORS RECOMMENDATIONS
1	zz/000	TO STRAIGHT OUT FRONT RH PILLAR & SILL PANEL <i>new</i>	600.00 <i>/</i>	
2	zz/000	RESPRAY FRONT RH PILLAR & SILL PANEL <i>new</i>	780.00 <i>/</i>	

TOTAL LABOUR CHARGES

1,380.00

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REG NO. SNG9411K

S/NO	PARTS DESCRIPTION	PARTS NO.	NETT	LIST	S/NETT	S/LIST	REMARKS
1	HINGE REAR DOOR LOWER,RIGHT	60479FG022				44.40	✓
2						-	
3						-	
4						-	
5						-	
6						-	
7						-	
8						-	
9						-	
10						-	
11						-	
12						-	
13						-	
14						-	
15						-	
16						-	
17						-	
18						-	
SUB TOTAL			0.00	0.00	0.00	44.40	
LESS DISCOUNT (S/LIST LESS - 20%)			0.00	0.00	0.00	8.88	
GRAND TOTAL			0.00	0.00	0.00	35.52	
OVERALL TOTAL			35.52				

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED