

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCF/11/23001082/493

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJF 6500J

at Workshop m/s Convergence

of _____

Insured: SML 45986

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 3500

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 5552

Date: _____ Person Contacted: LTA 901

Vehicle: IN / OUT

Date / Time Action / Instruction Dep 11k.

Col used 24-04-2023

3.1 Smith plus nett \$2599

4/5 2200 in hand Jeremy

Veh No: SJF 6500J Yr Regn: 25/04/08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Car

Make: Mit Col plus c.c 1499

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 100 R3 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYL2223W82000470

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55-R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 09/01/23 D.O.I. 2/2/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rk

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

CONVERGENCE AUTOMOTIVE
39 WOODLANDS CLOSE, MEGA@WOODLANDS
#01-24 SINGAPORE 737856
TEL: 69932080
ATT: JEREMY HP: 98888119

Estimate for SJF6500J(Mitsubishi Colt)

not allowed
den
2/1/23
2/5 & 2200/
6 days.

1 REAR BUMPER	DD	732	\$988.00	/
2 REAR BUMPER CORNER RETAINER L/R	11		\$96.00	X
2 REAR BUMPER INNER SHIELD L/R	11		\$88.00	X
2 REAR BUMPER REFLECTOR L/R	11		\$234.00	X
2 REAR BUMPER SIDE RETAINER L/R	sent		\$58.00	/
1 REAR END PANEL	DD	418	\$568.00	/
1 REAR END PANEL TOP GARNISH	twi		\$148.00	/
1 REAR END PANEL LOCK STRIKER	11		\$28.00	X
1 REAR EXHAUST GASKET	11		\$25.00	X
3 REAR EXHAUST RUBBER MOUNTING	11		\$150.00	X
1 REAR EXHAUST BOX	11		\$659.00	X
1 TAILGATE	DD		\$1,002.00	/
1 TAILGATE INNER HANDLE	11		\$108.00	X
1 TAILGATE INNER HANDLE SWITCH	11		\$58.00	X
1 TAILGATE INNER TRIM BOARD	de/cen		\$276.00	/
1 TAILGATE LOCK	DD/SM	205	\$370.00	/
2 TAILGATE NUMBER PLATE LAMP L/R	11		\$125.00	X
1 TAILGATE OUTER GARNISH	11		\$146.00	X
10 TAILGATE OUTER GARNISH CLIP	11		\$50.00	X
1 TAILGATE OUTER LOCK HANDLE	11		\$85.00	X
2 TAILGATE REFLECTOR LAMP L/R	11		\$458.00	X
2 TAILGATE RUBBER STOPPER L/R	11		\$48.00	X
1 TAILGATE WEATHER STRIPE	11		\$236.00	X
2 TAILGATE INNER WINDSCREEN GARNISH L/R	11		\$124.00	X
1 TAILGATE INNER WINDSCREEN TOP GARNISH	11		\$96.00	X
1 TAILGATE WINDSCREEN MOULDING	RM	86.00	\$175.00	/
2 TAILLAMP INNER PANEL L/R	11		\$422.00	X
2 TAILLAMP L/R	11		\$758.00	X
1 SPARE TYRE PANEL TOOLS TRAY	11		\$418.00	X
1 SPARE TYRE PANEL TOP BOARD	11		\$332.00	X
1 SPARE TYRE PANEL	R		\$1,002.00	X
			\$9,331.00	
			\$933.10	
			\$8,397.90	

Less 10%

1 set	REAR BUMPER CLIP	RM	\$50.00	30
1 set	REVERSE SENSOR	SM	\$300.00	X
	TAILGATE INNER TRIM CLIP	11	\$50.00	X
	REAR NUMBER PLATE	sent	\$50.00	40
	WINDSCREEN SEALANT	RM	\$120.00	40
	SPARE TYRE PANEL INSULATION MAT	11	\$350.00	X

WIRING CHECK
 REINSTALL REAR WINDSCREEN
 REMOVE & REFIT RER UPHOLSTERY
 PANEL BEATING ON DAMAGED PORTION
 SPRAY PAINTING ON DAMAGED PORTION
 REMOVE & REFIT EXHAUST PIPE
 ANTI RUST

	<u>\$920.00</u>
\$120.00	20
\$200.00	120
\$180.00	80
\$1,700.00	800
\$1,500.00	800
11 \$120.00	X
\$200.00	60
<u>\$4,020.00</u>	

Total

\$13,337.90

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-2928
 102
2632.50
 110
 1880
4622.50
 202
 3698