

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 03 Feb 2023

Preliminary Advice

Vehicle No	: SMW6356J	Accident Date	: 19/01/2023
Make	: NISSAN SYLPHY	Policy No.	: SP2002871503
Assignment Date	: 02/02/2023	Excess	: S\$600.00
Date of Inspection	: DESKTOP SURVEY	Est. Duration of Repair	: 4
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,124.50
Revised Amount	:S\$	2,277.00
Check Items (Estimated)	:S\$	1,259.50
Total	:S\$	3,536.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	41,867.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,133.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.