

C

123



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DLAU SOH YIN
C/O 176 SIN MING DRIVE #01-06/07c/o
SIN MING AUTO CARE 575721Attention : Motor Claim Department
Contact : 97334880

Not Authorized
11 days @ 2300/hr
Running After Repair
4 days

Estimate : ES012557

Date : 01/02/2023
Vehicle Num. : SKZ 233C
Make/Model : HONDA VEZEL 1.5X-2016
Chassis/Eng# : RU11108392
Accident Date : 13/01/2023
Claim No. :
Reference : TP - QBE AGT CHINA TAIPING
Policy No. : 8-V0025056-MVA

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 PC	REAR WINDSCREEN GLASS MOULDING		
2.	1 PC	TAILGATE		
3.	1 PC	TAILGATE WEATHERSTRIP		
4.	1 PC	TAILGATE LOCK		
5.	1 PC	TAILGATE EMBLEM (VEZEL)		
6.	1 PC	TAILGATE EMBLEM (HYBRID)		
7.	1 PC	REAR BUMPER		
8.	2 PC	REAR BUMPER SIDE RETAINER	42.00	
9.	1 PC	ANTENNA SENSOR		
10.	1 PC	BUZZER SENSOR		
11.	1 PC	REAR END PANEL		
12.	1 PC	REAR END PANEL TOP GARNISH		
13.	1 PC	REAR BUMPER UNDER COVER (CENTRE)		

List TotalS\$:

20.00% Discount S\$:

3,850.00

770.00

3,080.00

SPECIAL NETT ITEMS :		
1.	1 PC	REAR WINDSCREEN GLASS SEALANT
2.	1 PC	REAR WINDSCREEN INNER INNER SEAL

Mc 40.00 ✓
Mc 80.00 305m

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: **Page 2/2**
GST Reg. No.: 199501140D

LAU SOH YIN
C/O 176 SIN MING DRIVE #01-06/07c/o
SIN MING AUTO CARE 575721

Attention : Motor Claim Department

Contact : 97334880

Estimate : ES012557

Date : 01/02/2023
Vehicle Num. : SKZ 233C
Make/Model : HONDA VEZEL 1.5X-2016
Chassis/Eng# : RU11108392
Accident Date : ~~12/01/2023~~
Claim No. :
Reference : TP - QBE AGT CHINA TAIPING
Policy No. : 8-V0025056-MVA

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

3.	1 PC	TAILGATE SEALANT		
4.	1 SET	TAILGATE INNER TRIM CLIP		
5.	1 SET	REAR BUMPER CLIP		
6.	1 PC	REAR BUMPER CENTER CHROME		
7.	1 PC	REVERSE SENSOR		
8.	1 SET	REAR END PANEL TOP GARNISH CLIP		
9.	2 PC	REAR BUMPER REFLECTOR CHROME		

100.00	301m
60.00	X
60.00	✓
150.00	✓
280.00	X
60.00	X
360.00	X
180.00	
1,190.00	

Special Nett Total S\$:

LABOUR :

- TO CHECK WIRING
- TO REMOVE/REFIX REAR WINDSCREEN GLASS
- TO TRANSFER TAILGATE MECHANISM
- TO FIT REVERSE SENSOR ON NEW BUMPER
- TO RUSTPROOF ACCIDENT DAMAGE AREA
- TO APPLY BODY SEALANT TO CAR JOINTS
- TO REMOVE INNER TRIM, GARNISH AND ETC TO FACILATE, REPAIR AND FIX BCK
- TO REMOVE NESSERY PARTS TO CUT OUT END PANEL, REPAIR END PANEL REWELD END PANEL, REPALCE ACCIDENT DAMAGE, PARTS ALIGN THE SAME
- TO PUTTY AND RESPRAY ACCIDENT DAMAGE ARES

50.00	156
100.00	✓
100.00	601
120.00	301
100.00	301
120.00	X
200.00	X

Labour Total S\$:

1,000.00	4001
1,000.00	2201
2,790.00	

E. & O.E.

Total S\$: 7,060.00

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg