



FALCON-AIR

LAU SOH YIN
C/O 176 SIN MING DRIVE #01-06/07c/o
SIN MING AUTO CARE 575721

Attention : Motor Claim Department

Contact : 97334880

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No : 199501140D
GST Reg. No : 199501140D

Not Authorized
1/1 Eng &
Repair After Party
4 days

Estimate : ES012557

Date : 01/02/2023
Vehicle Num. : SKZ 233C
Make/Model : HONDA VEZEL 1.5X-2016
Chassis/Eng# : RU11108392
Accident Date : 13/01/2023
Claim No. :
Reference : TP - QBE AGT CHINA TAIPING
Policy No. : 8-V0025056-MVA

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- LIST ITEMS :
1. 1 PC REAR WINDSCREEN GLASS MOULDING
 2. 1 PC TAILGATE
 3. 1 PC TAILGATE WEATHERSTRIP
 4. 1 PC TAILGATE LOCK
 5. 1 PC TAILGATE EMBLEM (VEZEL)
 6. 1 PC TAILGATE EMBLEM (HYBRID)
 7. 1 PC REAR BUMPER
 8. 2 PC REAR BUMPER SIDE RETAINER
 9. 1 PC ANTENNA SENSOR
 10. 1 PC BUZZER SENSOR
 11. 1 PC REAR END PANEL
 12. 1 PC REAR END PANEL TOP GARNISH
 13. 1 PC REAR BUMPER UNDER COVER (CENTRE)

List TotalS\$:

20.00% Discount S\$:

168.00	✓
1,277.00	✓
148.00	X
168.00	X
68.00	✓
92.00	✓
745.00	✓
42.00	
84.00	X
110.00	X
115.00	X
492.00	X
138.00	X
245.00	X
3,850.00	
770.00	
3,080.00	

- SPECIAL NETT ITEMS :
1. 1 PC REAR WINDSCREEN GLASS SEALANT
 2. 1 PC REAR WINDSCREEN INNER INNER SEAL

40.00	✓
80.00	70.00

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6779-5665 Fax: 6779-1110



FALCON - AIR

LAU SOH YIN
C/O 176 SIN MING DRIVE #01-06/07c/b
SIN MING AUTO CARE 575721

Attention : Motor Claim Department
Contact : 97334880

Estimate : ES012557

Date : 01/02/2023
Vehicle Num. : SKZ 233C
Make/Model : HONDA VEZEL 1.5X-2016
Chassis/Eng# : RU11108392
Accident Date : 12/01/2023
Claim No. :
Reference : TP - QBE AGT CHINA TAIPING
Policy No. : 8-V0025056-MVA

S/N	Quantity	Particular	Unit Price	Amount S\$
3.	1 PC	TAILGATE SEALANT		100.00
4.	1 SET	TAILGATE INNER TRIM CLIP		60.00
5.	1 SET	REAR BUMPER CLIP		60.00
6.	1 PC	REAR BUMPER CENTER CHROME		150.00
7.	1 PC	REVERSE SENSOR		280.00
8.	1 SET	REAR END PANEL TOP GARNISH CLIP		60.00
9.	2 PC	REAR BUMPER REFLECTOR CHROME	180.00	360.00
Special Nett Total S\$:				1,190.00
LABOUR :				
TO CHECK WIRING				50.00
TO REMOVE/REFIX REAR WINDSCREEN GLASS				100.00
TO TRANSFER TAILGATE MECHANISM				100.00
TO FIT REVERSE SENSOR ON NEW BUMPER				120.00
TO RUSTPROOF ACCIDENT DAMAGE AREA				100.00
TO APPLY BODY SEALANT TO CAR JOINTS				120.00
TO REMOVE INNER TRIM, GARNISH AND ETC TO FACILATE, REPAIR AND FIX BCK				200.00
TO REMOVE NESSERY PARTS TO CUT OUT END PANEL, REPAIR END PANEL REWELD END PANEL, REPALCE ACCIDENT DAMAGE, PARTS ALIGN THE SAME				1,000.00
TO PUTTY AND RESPRAY ACCIDENT DAMAGE ARES				1,000.00
Labour Total S\$:				2,790.00

E. & O.E.

Total S\$: 7,060.00

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.