



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 7552A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	1,642.30	1,642.30
2	REAR BUMPER SIDE HOLDER @\$97.75	NOT NECESSARY	195.50	-
1	REAR BUMPER REINFORCEMENT	BENT	838.40	838.40
1	REAR BUMPER CENTRE GUIDE	CRACKED	227.70	227.70
1	REAR BUMPER LOWER GARNISH	DEFORMED	439.30	439.30
1	REAR BUMPER TOW COVER	NOT NECESSARY	56.40	-
2	REVERSE SENSOR @\$288.65	DAMAGED	577.30	577.30
2	REVERSE SENSOR HOLDER @\$28.75	NECESSARY	57.50	57.50
2	TAILLAMP @\$1339.80	CRACKED	2,679.60	1,534.00
1	REAR END PANEL	DENTED	1,565.20	1,361.00
1	REAR END PANEL TOP GARNISH	DEFORMED	302.50	302.50
1	BOOTLID	TO REPAIR SEE LABOUR	2,671.50	-
1	BOOTLID LOCK	DAMAGED	330.10	330.10
1	BOOTLID AUTO LOCK	NOT NECESSARY	799.30	-
1	BOOTLID WEATHERSTRIPE	CUT	373.76	373.76
1	MERCEDES BENZ LOGO	NECESSARY	89.70	89.70
1	AMG LOGO	NECESSARY	102.40	102.40
	LESS 10% DISCOUNT		-1,294.85	-787.60
			11,653.61	7,088.36
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER STICKER WRAP (SN)	NECESSARY	400.00	350.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	BOOTLID STICKER WRAP (SN)	NECESSARY	450.00	300.00
			980.00	780.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID.		1,200.00	700.00
	SPRAY PAINTING.		1,000.00	700.00

Report Ref No. CS/AGI23001092/Any3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING.		100.00	30.00
	TO APPLY TUFF COAT.		150.00	80.00
	TO REMOVE UPHOLSTERY.		150.00	80.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO TRANSFER BOOTLID FITTINGS.	NOT NECESSARY	150.00	-
	TO PERFORM DIAGNOSTIC TEST.	NOT NECESSARY	200.00	-
			3,050.00	1,640.00
<b>GRAND TOTAL</b>			<b>15,683.61</b>	<b>9,508.36</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,600.00</b>

Report Ref No. CS/AGI23001092/Any3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.