

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

XinYu

Aviary
Monday
no

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428

TEL: 62218611 FAX: 62241047
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 15/01/2023

Estimate No: EST2300040

Date: 30 Jan 2023

Veh Reg No: SKV8923M
Make/Model: HONDA VEZEL 1.5X A
Chasis No: RU11103224
Reg. Date: 07/10/2015
Your Ref No: SLB726L

Estimate Repair Cost to Vehicle No :SKV8923M

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR BOOT LID <i>Dented</i>	1,168.00	✓
2	1 PC REAR BOOTLID "VEZEL" EMBLEM <i>new</i>	35.80	✓
3	1 PC REAR WINDSCREEN RUBBER <i>new</i>	2869.20 125.00	✓
4	1 PC REAR BOOT LID LOCK <i>Dented</i>	187.00	✓
5	1 PC REAR BOOT LID TRIM <i>front Dented</i>	2295.36 215.00	✓
6	1 PC REAR BOOT LID RUBBER <i>ut</i>	186.90	✓
7	1 PC REAR END PANEL <i>Rear</i>	397.90	✓
8	1 PC REAR END PANEL TRIM <i>Dented</i>	126.20	✓
9	1 PC REAR BUMPER <i>Dented</i>	568.00	✓
10	1 PC REAR BUMPER UNDER COVER <i>Dented</i>	186.40	✓
	<i>1pc " buzzer 70.90</i>	3,196.20	
		Less 20%	639.24 2,556.96
	Special Net		
11	1 PC REAR WINDSCREEN SEALANT <i>3 new</i>	60.00	30
12	1 PC REAR WINDSCREEN SEALANT RUBBER	60.00	30
13	1 SET REAR BOOT LID TRIM CLIPS <i>new</i>	40.00	30
14	1 SET REAR END PANEL TRIM CLIPS <i>new</i>	30.00	10
15	1 SET REAR REVERSE SENSORS <i>Dented</i>	250.00	20
	<i>1 set 4 bumper under cover clip 60.00</i>	440.00	440.00
	Labour		
16	1 TO CHECK WIRING <i>new</i>	50.00	30
17	1 (REAR) TO REMOVE AND REFIT WINDSCREEN GLASS	120.00	✓
18	1 TO REMOVE AND REFIT REAR INNER TRIM	100.00	60
19	1 TO SPRAY OANEL SEALANT	100.00	X
20	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50
21	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	800.00	400

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE
SINGAPORE 069428

TEL: 62218611 FAX: 62241047
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 15/01/2023

Estimate No: EST2300040

Date: 30 Jan 2023

Veh Reg No: SKV8923M

Make/Model: HONDA VEZEL 1.5X A

Chasis No: RU11103224

Reg. Date: 07/10/2015

Your Ref No: SLB726L

Estimate Repair Cost to Vehicle No :SKV8923M

Quantity	Description	List Price	Amount
		SS	SS
22	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	500
	1160	2,250.00	2,250.00
Total			S\$ 5,246.96
Add GST @ 8%			419.76
Total Amount Payable			S\$ 5,666.72

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SIX HUNDRED SIXTY SIX AND CENTS SEVENTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li

1/s 06/02/23.

0\$ Pays.

total: 3785.36.

4/s: 3K ✓