

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan Kian Chuan

Date: 22 May 2023

Preliminary Advice

Insured Vehicle No	: XD1506X	Accident Date	: 18/01/2023
TP Vehicle No	: SLK7492S	Assignment Date	: 02/02/2023
Make	: PEUGEOT 5008	Est. Duration of Repair	: 1
Date of Inspection	: 10/02/2023		
Inspection At	: MIRAGE MOTORWERKZ PTE LTD (HQ) 10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE SINGAPORE 417868		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,438.83
Revised Amount	:S\$	1,084.01
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,084.01

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.