

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|---|---|--------------------|---------------------|--|
| | INCOME INSURAN | NCE LTD | Ref: | CS/INC23001102/Awy3 | |
| | 75 BRAS BASAH FINCOME CENTRE | ROAD SINGAPORE 189557 | Date | : 02/02/2023 | |
| | | | Code | e: INC | |
| 1. | . Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | FBR 3750E | Veh. Inspected | SNH 9783G | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | MT/1207569-002 | Excess (\$) | 0.00 | |
| | Assign From | HAZALYSA BINTE IBRAHIM | Assign Date | 02/02/2023 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | | c.c | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | | Colour | | |
| | Odometer | - | Steering | | |
| | Brakes | | Modification | | |
| | General | | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | | | mm | |
| | L/H Front Tyre | | | mm | |
| | R/H Rear Tyre | | | mm | |
| | L/H Rear Tyre | | | mm | |
| 4. | Description of Damages | | | | |
| | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 21/01/2023 | Inspection Date | 02/02/2023 | |
| | Survey held at | AUTO UNITED SG PTE LTD | | | |
| | | 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE | , SINGAPORE 417807 | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |