

SERVICE ESTIMATE

81321 - 000001
 Mr Lim Kok Leong
 134 St Patrick's Road
 #06-13

Singapore 424213

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Lim Kok Leong

SL: SERVICE SALES - PC

GST Reg.No: M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 01/02/2023

WIP No. . : 61081

Veh.In/Out:

*Tel.No. . : Mobile: 97916493

Reg.No. . : SMH1208R

Reg.date . : 31/12/2018

Mileage . : 0

Chassis No: SADFA2AX2K1Z45998

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE TAILGATE, REAR BUMP	0	4000.00	0		4,000.00 S	2000 ✓
	REAR DIFFUSER, SKID PLATE, REFLECTOR, PARKING SENSORS, LHR FENDER WIDENER, EMBLEMS, BRACKETS, CLIPS, ETC.						
800	TO BLEND AND SPRAY PAINT ON	0	2700.00	0		2,700.00 S	1800 ✓
	TAILGATE, REAR BUMPER, ETC.						
802	TO REPLACE REAR WINDSCREEN	0	1000.00	0		1,000.00 S	✓
0080	TO INSTALL REAR WINDSCREEN	0	280.00	0		280.00 S	✓
	SOLAR FILM						
802	TO TRANSFER TAILGATE MECHANISM	0	500.00	0		500.00 S	✓
280	TO CHECK WIRING INCLUDE	0	621.00	0		621.00 S	✓
	RESETTING OF ALL ELECTRICAL MODULES						
	PANEL-TAILGATE E-Pac <i>dc</i>	1.0 EA	3994.70			3,994.70 S	3595.23
	D PRIMER GLASS & P <i>dc</i>	1.0 EA	46.90			46.90 S	42.21
	SEALANT WINDSCREEN <i>dc</i>	2.0 EA	192.90			385.80 S	350.22
	GLASS-BACKLIGHT E-Pa <i>X</i>	1.0 EA	1128.10			1,128.10 S	1015.29

SERVICE ESTIMATE

81321 - C00001 SL: SERVICE SALES - PC

Mr Lim Kok Leong
134 St Patrick's Road
#06-13

Singapore 424213

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 01/02/2023

WIP No. : 61081

Veh.In/Out:

*Tel.No. : Mobile: 97916493

Reg.No. : SMH1208R

Reg.date : 31/12/2018

Mileage : 0

Chassis No: SADFA2AX2K1Z45998

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Lim Kok Leong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	COVER-BUMPER REAR <i>de /</i>	1.0 EA	2346.70			2,346.70 S	2112.03
	PANEL-VALLANCE <i>ser /</i>	1.0 EA	199.10			199.10 S	179.19
	BLADE-BUMPER <i>? ✓ at /</i>	1.0 EA	396.70			396.70 S	357.03
	MOULDING LH <i>? X nn</i>	1.0 EA	98.30			98.30 S	
	FINISHER LH <i>? ✓ ser /</i>	1.0 EA	541.30			541.30 S	487.17
	BRACKET-BUMPER LH <i>? X nn</i>	1.0 EA	156.60			156.60 S	
	MOUNTING-BRACKET LH <i>? X nn</i>	1.0 EA	134.30			134.30 S	
	MOUNTING-BRACKET CTR <i>? X nn</i>	1.0 EA	191.10			191.10 S	
	MOULDING LH <i>? ✓ ser /</i>	1.0 EA	268.60			268.60 S	241.74
	LAMP-FOG LH <i>ser /</i>	1.0 EA	293.10			293.10 S	263.79
	SENSOR <i>? X nn</i>	4.0 EA	365.60			1,462.40 S	
	BADGE - E-PACE <i>nn /</i>	1.0 EA	216.90			216.90 S	195.21
	BADGE - half leaper <i>nn /</i>	1.0 EA	203.60			203.60 S	183.24
	BADGE 'P200 AWD' <i>nn /</i>	1.0 EA	216.90			216.90 S	195.21
	SILENCER-EXHAUST <i>? X nn</i>	1.0 EA	5807.90			5,807.90 S	
	HEATSHIELD REAR <i>? ✓ at /</i>	1.0 EA	218.70			218.70 S	196.83
	HEATSHIELD REAR <i>? X nn</i>	1.0 EA	243.70			243.70 S	

SERVICE ESTIMATE

81321 - C00001
Mr Lim Kok Leong
134 St Patrick's Road
#06-13

SL: SERVICE SALES - PC

Singapore 424213

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Lim Kok Leong

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 3
Inv.date. : 01/02/2023
WIP No. . : 61081
Veh.In/Out:
*Tel.No. . : Mobile: 97916493
Reg.No. . : SMH1208R
Reg.date . : 31/12/2018
Mileage ... : 0
Chassis No: SADFA2AX2K1Z45998

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BEAM REAR XE ? X 11	1.0 EA	830.00			830.00	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Passer
Hp 9001068
5 days
06/02/23 @ 0930
Reg before part

Labour Total 9,101.00
Parts Total 19,381.40
Package Total 0.00

Gross Total. 23,482.40
Net..... 28,482.40
GST @ 8.0% 2,279.59
Total..... 30,761.00
Paid..... 0.00
Please Pay.. 30,761.00

GST: S=StdRated: O=OutOfScope; Z=ZeroRated; P=PreviousRate