
ASS	IGNMEN
Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No:	Veh No: GBK7694U. Yr Regn: 2020 / NOV Type: M.Car / M.Cycle / Bus / Var) / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: Toyota Hiace c.c 2982
at Workshop m/s of insured: Policy No. Claims No.	Colour While. A/C: Insured / Std / NI / NA Sp.Reading T/Radio: Insured / Std / NI / NA Eng/No: C/No: JTFHT02 P x 0 02*5076,2 Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: (Client's Record) Make of Veh:	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nil)S/Rim / STD A/Rim or Tyre Size: F: 195 R15 C-
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: DAC Accident Rport: Consistent?: Yes or No	R: 1957-15C BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/ TOYO/YOKO or Front R/Bal. R/Bal. mm R/Bal. mm
Consistent?: Yes or No st. Repairs: 30 days Res.: Yes or No um Sum: % 3 Val.: Yes or No A / REV / REP. / 24 HRS Vehicle: IN / OUT	L/Bal. 06 mm D.O.A. D.O.I. 02 32 23 Survey held at Auto United. Des. of Damages Frt Rear O/S N/S U/C Rooftop or
	The U/C / Chassis frame / Body Structure affected due to collision. Days with repairer. (Red 26, 816.55, 41%)
MV: 80C. PV: 20.8K Nett: 5921C	
	Days Of Repair:30

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle


Owner ID Type:	Company
Owner ID:	123N
Vehicle Details	
Vehicle No.:	GBK7694U
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	1KDB062019
Chassis No.:	JTFHT02PX00250762
Maximum Power Output:	÷
Open Market Value:	\$28,235.00
Original Registration Date:	12 Nov 2020
First Registration Date:	12 Nov 2020
Transfer Count:	1
Actual ARF Paid:	\$1,412.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Nov 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,644.00
COE Rebate Amount:	\$20,708.00
Total Rebate Amount:	\$20,708.00

The information contained herein is correct as at 03 Feb 2023



Compare





Depreciation ~

Reg Date ✓

« Back (123) Next »

Eng Cap∨

Mileage

Veh Type ✓

Status

20 v results/page

✓ Model

For old advertisements, view Expired ads

Price V

Sgcarmart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used hiace, hiace Singapore, used hiace Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on Sgcarmart.com are gathered from sources and based on algorithms that are believed by Sgcarmart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. Sgcarmart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information

Terms of Service Privacy Policy Personal Data Protection Statement ©2004-2023 Sgcarmart, Singapore. All rights reserved.





SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

01/02/2023 17:59 (SGT)

Both Policyholder and Actual Driver

31/01/2023 15:50 (SGT)

Woodlands Ave 12, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBK7694U

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Yes

CRYSTAL PLUMBING & INTERIOR DESIGN STUDIO PTE. LTD

Company Reg No

Email Address

Mobile Phone No

Alternative Phone No

2XXXXXX123N

CRYSTALPLUMBING2672@GMAIL.COM

(Phone) +65-96417073

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to your vehicle?

CC

Vehicle Category

Transmission

Toyota

Hiace

Employment

No - Claiming third party

Commercial vehicle

Manual

2982

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Income Insurance Limited

5128299093

DRIVER

Name of Driver

Passport No/FIN

Date Of Birth

IQBAL SINGH GXXXX219K 05/09/1986



Occupation Date Of Driving Pass Driving experience

Gender

Mobile Number Alt. Phone Number **Email Address**

Address Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Chain Collision Raining Wet

Outdoor

Male

757443

Employee

No

No

19/02/2021

1 YEAR AND 11 MONTHS

IQBALSINGHSGP@GMAIL.COM 51 ADMIRALTY RD WEST

#02-18 COCHRANE LODGE 1

(Phone) +65-98947597

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 5 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name

Translator's ID Translator's phone number

Translator's email Original language used in the statement

PASSENGER 1

Name Gender **BOOPATHI TAMILARASAN** Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? Police Station Name Police Station Phone No Alt. Police Station Phone No Police Station Address

Was notice of intended Prosecution given? If yes, against whom?

(Fax) +65-65474900 10 Ubi Avenue 3 Singapore 408865 No

Traffic Police

(Phone) +65-65470000

Yes

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN AND POLICE REPORT ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD1875E Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YQ5972B Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GBE7775B Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Commercial vehicle Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration NumberSLX5129ZVehicle Manufacturer-Vehicle Model-Vehicle Variant-Vehicle Colour-Vehicle CategoryPrivate carName of Driver-Contact Number-Address-Address complement-

na in ing skini	
Postcode	-
Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person **IQBAL SINGH** Gender Male Phone No (Phone) +65-98947597 Address Address Complement Post Code Approximate Age Years Old Injuries Sustained 5 DAYS MC Injured person in which vehicle? GBK7694U Were seat belts worn? Yes Was this injured conveyed to hospital by ambulance? No

INJURED 2

Name of injured person Gender Phone No Address Address Complement Post Code Approximate Age Years Old Injuries Sustained Injured person in which vehicle? Were seat belts worn?	BOOPATHI TAMILARASAN Male 5 DAYS MC GBK7694U Yes
Was this injured conveyed to hospital by ambulance?	Yes No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willul misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s). who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my daims including the settlement of the claims and any necessary investigations relating to the claims:

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or (including the) illaw firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Sic te & Time

Isbal Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personne [Name as in NRICHD card]

Sketch Plan A-GBK7694U wood lands XD 1875 E Ave SLX51292 5

escribe Circumstance of the Accident	
Follow Police Report	
	The state of the s
	and the state of t
Declaration	CULCE
I/We declare the foregoing particulars are true in every respect.	788
to I rebed Singh	Z (00 Reg No.) (7 2 2013 16685 G)
	7
Policyholder's Standure / Date & Time Onver's Signature (# driver is not the policyholder) / Date & Time	Winessed by Reporting Circle Personnel (Name as in NRICAD care)

-





1 of 3 Report No. T/20230131/7070

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time 31/01/2023		ide:	Vide Report No.:		Station Diary No.:	
Informant'	s Particul	ars				
Name of In IQBAL SIN		4	Address:			
ID Type / II	O No.:		Contact No.:			
FIN NO / G8067219K			Home/Office: Mobile: 98947597			
Nationality:			Email:			
INDIAN			iqbalsinghsgp@gmail.com			
Sex:	Age:	Date of Birth:	Type of Informant:			
Male	36	05/09/1986	Driver			
Race:		1	Language: Institution / School Na		School Name:	
Indian			English			
Occupation:			Driving Licence Information:			
Plumber			Class: 3	Date of Ex	piry:	

General Information of the Accident						
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/01/2023 15:50)	Type of Location: Straight Road	
Location:			2			
WOODLANDS AV	/ENUE 12					
Weather:	12	Road Surface:		Road	Speed Limit:	
Drizzling		Wet				
Traffic Flow:		Traffic Control:		Traffi	c Volume:	
One Way	one Way Not Controlled Modera			erate		
Type of Collision: Between Moving	Vehicles - Head To Re	ear			ne conveyed by ulance:	

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Conditio	No of
GBK7694U	Van					1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20230131/7070

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Driver							
Name	IQBAL SINGH			IQBAL SINGH ID No.		. G8067219K	
Related Vehicle	GBK7694U (Van)			Conta	ct No.	98947597	
Hospital/Clinic	NIL			Class Driving Licent Expiry	g ce &	Class: 3 Date of Expiry: NIL	
Date	31/01/2023		Date	31/01		/2023	
No. of Days granted Medical Leave 05			Degree of		Sligh	t	

Brief Details.

On the above mentioned date time and location. I was traveling straight with 1 passenger on board. As the vehicle Infront slow down hence I follow suit. Seconds later I felt a huge impact from the rear and as I alighted I realized it was a chain collision of 5 vehicles. Vehicle(b) collided onto the rear of my vehicle (a) causing damages to my vehicle(a)

Vehicle(b) collided onto vehicle(a) from the rear, pushing it to collide with vehicle(c) and than vehicle(c) collided onto vehicle (d) and vehicle(d) collide onto vehicle (e)

My passenger and I felt pain on our neck, back, hand and leg. So we went to our family physicians clinic to seek consultation and was given 5 days mc each.

Vehicle(a) gbk7694u

Vehicle(b) xd1875e

Vehicle(c) yq5972b

Vehicle(d) gbe7775b

Vehicle (e) slx5129l

Passenger :boopathi tamilarasan 5days mc





3 of 3

Report No. T/20230131/7070

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

_					
C	10	-	h	D	lan
O	75			Г	all

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter:	Date/Time:
Not applicable	31/01/2023 18:59
Officer In Charge Of Case:	Classification Of Case:
TP / TPIB /	
MOHAMAD ZULFAZDLI BIN ABDULLAH	
Contact No.: 65476204	



AUTO UNITED SG PTE LTD

13 Kaki Bukit Rd 4, #03-29, Bartley Biz Centre, Singapore 417807 Tel. 6844 1184

VEHICLE NO

: GBK7694J

2020

VEHICLE MODEL

: TOYOTA HIACE

CHASSIS NO

: JTFHT02PX00250762

CLAIM DETAILS: PARTS

ITEMS	QTY	UNIT PRICE	TOTAL	
1 FRONT BUMPER DISULC	1	\$ 541.20	\$ 541.20	-
2 FRONT BUMPER SIDE HOLDER	2	\$ 66.50	\$ 133.00	7
3 FRONT BUMPER SIDE COVER LIX DELA	2	\$ 62.10	\$ 124.20	6
4 FRONT BUMPER LOWER GRILLE DISTORTED	1	\$ 178.10	\$ 178.10	1
5 FRONT BUMPER REINFORCEMENT Devoted	1	\$ 361.00	\$ 361.00	1
6 FRONT BUMPER REINFORCEMENT STAY Distorted	2	\$ 198.00	\$ 396.00	1-
7 FRONT BUMPER TOP BEAM BENT.	1	\$ 189.60	\$ 189.60	1
8 FRONT BUMPER BRACKET BENT	2	\$ 98.20	\$ 196.40	
9 FRONT BUMPER TOW COVER Dela	1	\$ 24.80	\$ 24.80	1
10 FRONT GRILLE Smushed	1	\$ 496.80	\$ 496.80	1
11 FRONT GRILLE TOP MOULDING & SAMPLES	1	\$ 198.60	\$ 198.60	1
12 FRONT GRILLE LOWER MOULDING	1	\$ 214.70	\$ 214.70	1
13 HEADLAMP Cricked	2	\$ 745.20	\$ 1,490.40	-
14 BONNET (1) Storfed	1	\$ 872.90	\$ 872.90	1
15 BONNET LOGO New	1	\$ 75.00	\$ 75.00	1
16 BONNET HINGE Bent	2	\$ 56.00	\$ 112.00	1
17 BONNET LOCK	1	\$ 88.90	\$ 88.90	1
18 FRONT BRACE PANEL Sect.	1	\$ 98.40	\$ 98.40	v
19 FRONT CORNER PANEL LA Distorted	2	\$ 376.50	\$ 753.00	32
20 FRONT SUPPORT PANEL Distorted	1	\$ 464.20	\$ 464.20	-
21 FRONT SUPPORT PANEL TOP COVER Defond	1	\$ 187.40	\$ 187.40	
22 AIR CON CONDENSER Distorted.	1	\$ 1,216.10	\$ 1,216.10	
23 AIR CON CONDENSER TOP BRACKET BUT	2	\$ 38.20	\$ 76.40	-
24 AIR CON CONDENSER LOWER MOUNTING M	2	\$ 25.40	\$ 50.80	
25 AIR CON CONDENSER DISCHARGE PIPE	1	\$ 275.90	\$ 275.90	
26 AIR CON CONDENSER SUCTION PIPE BENT	1	\$ 285.80	\$ 285.80	
27 AIR CON CONDENSER LIQUID PIPE	1	\$ 205.60	\$ 205.60	-
28 AIR CON FAN ASSY THE NEW	1	\$ 415.60	\$ 415.60	X
29 RADIATOR Devices.	1	\$ 1,495.00	\$ 1,495.00	1
30 RADIATOR TOP MOUNTING 4200	2	\$ 20.90	\$ 41.80	
31 RADIATOR LOWER MOUNTING	2	\$ 22.50	\$ 45.00	
32 RADIATOR TOP HOSE THE N	1	\$ 75.20	\$ 75.20	4
33 RADIATOR SPARE TANK Crued	1	\$ 140.90	\$ 140.90	
34 RADIATOR FAN ASSY NE NEW	1	\$ 428.90	\$ 428.90	1
35 FAN COMBINATION SHROUD SMUSLES	1	\$ 295.00	\$ 295.00	
36 INTERCOOLER Devted	1	\$ 1,289.80	\$ 1,289.80	4

38 MYPER WASHER TANK 1 5 139.30 8 139.39	27/11/750000/50 00000000	-	·		
39 UNPER WASHER TANK MOTOR AF AW 1 5 128,90 5 123,90 4	20			\$ 139.30	J.
40		1	\$ 89.70	\$ 89.70	
41 WIPER MOTOR 1 5 890.40 5 890.40 6		1	\$ 128.90	\$ 128.90	12.
42 WIPER MOTOR LINKAGE 43 FRONT DOOR STEP PAIL 44 FRONT HOOR STEP PAIL GRRISH LY 45 FRONT HOOR STEP PAIL GRRISH LY 47 AIR CON BLOWER 47 AIR CON BLOWER 47 AIR CON BLOWER 48 AIR CON EVAPORATOR 49 STEERING AIR BAG SENSOR 50 STEERING AIR BAG SENSOR 51 S 1,466.10 52 S 20.50 53 BASHBOARD RINFORCIMENT 51 S 245.90 52 S 245.90 52 S 250.50 53 AIR SAG SENSOR 52 S 265.90 53 DASHBOARD RINFORCIMENT 54 S 245.90 55 DASHBOARD RINFORCIMENT 55 DASHBOARD SIDE GRANISH 55 DASHBOARD SIDE GRANISH 55 DASHBOARD SIDE GRANISH 55 DASHBOARD SIDE GRANISH 56 DASHBOARD SIDE GRANISH 57 DASHBOARD SIDE GRANISH 57 DASHBOARD SIDE GRANISH 58 AIR BAG SELU 59 FRONT SKAT BELT 50 AIR SAG SELU 51 FRONT WINDSCREEN 52 S 260.00 53 RAR BUMPER LOWER BRACKET 54 S 260.00 56 RAR BUMPER LOWER BRACKET 57 DASHBOARD RANE LINKER 58 S 28 S 38.40 59 FRONT SKAT BELT 50 AIR SAG SELU 50 FRONT WINDSCREEN 50 AIR SAG SELU 51 S 260.00 51		1	\$ 435.50	\$ 435.50	
44 FRONT LID DOOR PILLAR 1		1	\$ 890.40	\$ 890.40	
44 FRONT LH DOOR PILLAR		1	\$ 294.50	\$ 294.50	
46 FRONT LH DOOR PILLAR INNER PLANS 1 5 428.10 7 428.10 4 428.10 4 428.10 5 428.10 5 428.10 5 428.10 7 428.10 6 FRONT DOOR STEP PANEL GARNISH LH DOLL 2 5 2 5 20.55 5 441.00 120.50 5 441.00 1		2	\$ 1,438.50	\$ 2,877.00	7 X
40 FRONT DOOR STEP PANEL GARNISH 1		1	\$ 765.80	\$ 765.80	
46 FRONT DOOR STEP PANEL GARNISH 1 2 3 220.50 5 441:00 20 50 50 441:00 20 50 50 441:00 20 50 50 441:00 20 50 50 441:00 20 50 50 441:00 20 50 50 441:00 20 50 50 50 50 50 50	45 FRONT LH DOOR PILLAR INNER Pers	1	\$ 428.10	† ·	- L
47 AIR CON BLOWER	46 FRONT DOOR STEP PANEL GARNISH LH Delad	2	 		
48 AR CON EVAPORATOR 1 5 1,466.10 3 1,466.10 5 5 5 5 5 5 5 5 5	47 AIR CON BLOWER GRAVIA	1		+	_
49 STEERING AIR BAG	48 AIR CON EVAPORATOR	1			
SO STEERING AIR BAG SENSOR	49 STEERING AIR BAG	1			_
SI STEERING AIR BAG ANTI CLOCK SPRING 1 S 398.90 S 398.90 S 208.80	50 STEERING AIR BAG SENSOR Avenued	1		 	- ,
S2 DASHBOARD	51 STEERING AIR BAG ANTI CLOCK SPRING	1			- /
SS DASHBOARD AIR BAG	52 DASHBOARD -ON	1		+	- /
SA DASHBOARD CEINFORCEMENT Sent 1 5 680.80 5 680.30 5 5 DASHBOARD CENTRE CONSOLE 1 5 398.40 398.40 5 50 DASHBOARD SIDE GARNISH THE CONSOLE 1 5 299.50 299.50 5 299.50 5 5 209.50 5 299.50 299.50	53 DASHBOARD AIR BAG Acclineded	1			_
1 S 398.40 S 388.40 S 388.40 S 50 S	54 DASHBOARD REINFORCEMENT Bend				
SECONSHIBOARD SIDE GARNISH					-
S	56 DASHBOARD SIDE GARNISH	1		-	-
S	57 DASHBOARD SIDE COVER			-	-
Separation Sep	58 AIR BAG ECU Arthulla	1			-
60 PRONT WINDSCREEN MOULDING	59 FRONT SEAT BELT Archited	2			
62 REAR NUMBER PLATE LAMP AFF W. 2 5 58.10 5 116.20 63 REAR BUMPER DE HOLDER	60 FRONT WINDSCREEN Cuclic				
62 REAR NUMBER PLATE LAMP ARE NOT 15 525.90 \$ 525.90 63 REAR BUMPER DE	61 FRONT WINDSCREEN MOULDING MA	1			
1 S 525.90 S 525.90	62 REAR NUMBER PLATE LAMP NEW	2			
64 REAR BUMPER SIDE HOLDER 65 REAR BUMPER LOWER BRACKET 66 REAR END PANEL OUTER 72 S 984.50 67 REAR END PANEL INNER 1 S 994.50 68 REAR END PANEL TOP METAL STRIPE 1 S 288.50 69 REAR END PANEL SIDE EXTENSION 1 S 288.50 69 REAR END PANEL SIDE EXTENSION 1 S 288.50 70 TAILLAMP 1 S 363.40 71 TAILLAMP PANEL INNER 1 S 391.40 72 TAILLAMP PANEL INNER 73 TAILLAMP PANEL INNER 74 TAILLAMP LOWER APRON 75 TAILLAMP LOWER APRON 76 TAILLAMP LOWER APRON 77 TAILLAMP LOWER APRON RETAINER 78 TAILGATE 19 S 399.10 78 TAILGATE LOCK 79 TAILGATE LOCK 10 S 399.10 78 TAILGATE WEATHERSTRIPE 11 S 398.50 79 TAILGATE LOCK ACTUATOR 12 S 364.60 79 TAILGATE HINGE 13 S 399.10 78 TAILGATE HINGE 24 S 364.60 79 TAILGATE OUTER GARNISH 25 TAILGATE WEATHERSTRIPE 16 S 365.00 79 TAILGATE OUTER GARNISH 11 S 69.80 70 S 69.80 84 TAILGATE WEATHERSTRIPE 11 S 365.00 85 TAILGATE WEATHERSTRIPE 12 S 365.00 86 TAILGATE OUTER GARNISH 13 S 365.00 87 TAILGATE OUTER GARNISH 14 S 485.90 88 TAILGATE WIPER MOTOR 15 S 485.90 88 TAILGATE TOP REFLECTOR 16 S 77.50 88 TAILGATE GASS MOULDING 17 S 17.50 18 TAILGATE GASS MOULDING 18 TAILGATE GASS MOULDING 19 TAILGATE CASS MOULDING 10 S 76.08 11 S 172.50 11 S 172.50 12 S 77.50 13 S 172.50 14 S 172.50 15 TAILGATE CASS MOULDING 15 S 172.50 16 S 172.50 17 S 172.50 1	63 REAR BUMPER Dela	1		<u> </u>	- '/
65 REAR BUMPER LOWER BRACKET REAL 4 \$ 18.00 \$ 72.00 66 REAR END PANEL OUTER 1 \$ 492.50 \$ 492.50 \$ 492.50 \$ 72.00 67 REAR END PANEL INNER 1 \$ 994.50 \$ 994.50 \$ 994.50 \$ 88 REAR END PANEL TOP METAL STRIPE REAL 1 \$ 288.50 \$ 288.50 \$ 288.50 \$ 26.10 \$ 724.20 \$ 362.10 \$	64 REAR BUMPER SIDE HOLDER	2		 	- ,
1 S 492.50 S 492.50 C 492.50 C 492.50 C 67 REAR END PANEL INNER 1 S 994.50 S 994.50 S 994.50 C 68 REAR END PANEL SIDE EXTENSION L.H. Deuted 2 S 362.10 S 724.20 C 70 TAILLAMP LOUTER L.H. Deuted 2 S 363.40 S 726.80 C 726.80 C 727.20 C 70 TAILLAMP PANEL OUTER L.H. Deuted 2 S 363.40 S 726.80 C 727.20 C 727.	65 REAR BUMPER LOWER BRACKET Red	4		-	
67 REAR END PANEL INNER 68 REAR END PANEL TOP METAL STRIPE 1 \$ 288.50 \$ 288.50 69 REAR END PANEL SIDE EXTENSION LHD DELCC 70 TAILLAMP LNO SMUSCA RHD TO REAL STRIPE 71 TAILLAMP LNO SMUSCA RHD TO REAL STRIPE 72 TAILLAMP PANEL OUTER LHD DELCC 73 TAILLAMP PANEL OUTER LHD DELCC 74 TAILLAMP LOWER APRON LHD DELCC 75 TAILLAMP LOWER APRON RETAINER RHD 76 TAILLAMP LOWER APRON RETAINER RHD 77 TAILLAMP LOWER APRON RETAINER RHD 78 TAILLAMP LOWER APRON RETAINER RHD 79 TAILGATE LOCK ACTUATOR 70 TAILLAMP LOCK ACTUATOR 71 TAILLAMP LOCK ACTUATOR 72 TAILLAMP LOCK ACTUATOR 73 TAILLAMP LOCK ACTUATOR 74 TAILLAMP LOCK ACTUATOR 75 TAILGATE WEATHERSTRIPE 76 TAILGATE WEATHERSTRIPE 77 TAILGATE INNER TRIM BOARD 78 TAILGATE INNER TRIM BOARD 79 TAILGATE INNER TRIM BOARD 10 \$ 387.30 11 \$ 165.50 12 \$ 364.60 13 \$ 399.10 14 \$ 387.30 15 \$ 387.30 16 \$ 369.80 17 TAILGATE WIPER MOTOR 18 TAILGATE WIPER MOTOR 19 \$ 485.90 10 \$ 485.90 11 \$ 485.90 12 \$ 485.90 13 TAILGATE WIPER MOTOR 14 \$ 485.90 15 \$ 49.90 16 \$ 40.90 17 TAILGATE GLASS MOULDING 17 TAILGATE GLASS MOULDING 18 TAILGATE GLASS MOULDING 19 TAILGATE GLASS MOULDING 10 TOYOTA LOGO 11 \$ 60.80 12 \$ 60.80 13 TAILGATE MONORMEN 14 \$ 60.80 15 TAILGATE MONORMEN 15 TAILGATE GLASS MOULDING 16 TAILGATE MAN HAD 17 TAILGATE GLASS MOULDING 18 TAILGATE GLASS MOULDING 19 TAILGATE GLASS MOULDING 10 TOYOTA LOGO 11 \$ 60.80 12 \$ 60.80 13 TAILGATE MONORMEN 14 \$ 60.80 15 TAILGATE GLASS MOULDING 15 TAILGATE GLASS MOULDING 16 TAILGATE GLASS MOULDING 17 TAILGATE GLASS MOULDING 18 TAILGATE GLASS MOULDING 19 TAILGATE GLASS MOULDING 10 TOYOTA LOGO 11 \$ 60.80 12 TAILGATE MONORMEN 13 TAILGATE GLASS MOULDING 14 \$ 60.80 15 TAILGATE GLASS MOULDING 15 TAILGATE GLASS MOULDING 15 TAILGATE GLASS MOULDING 16 TAILGATE GLASS MOULDING 17 TAILGATE GLASS MOULDING 18 TAILGATE GLASS MOULDING 19 TAILGATE GLASS MOULDING 10 TOYOTA LOGO 11 \$ 60.80 11 \$ 60.80 12 TAILGATE GLASS MOULDING 15 TAILGATE GLASS MOULDING 16 TAILGATE GLASS MOULDING 17 TAILGATE GLASS MOULD	66 REAR END PANEL OUTER 2 Dochod	1		-	-
68 REAR END PANEL TOP METAL STRIPE 69 REAR END PANEL SIDE EXTENSION H Device 2 \$ 362.10 \$ 724.20 \$ 362.10 \$ 724.20 \$ 362.10 \$ 724.20 \$ 362.10 \$ 724.20 \$ 362.10 \$ 724.20 \$ 362.10 \$ 724.20 \$ 362.10 \$ 725.80 \$ 71 TAILLAMP LID SMADLE LID	67 REAR END PANEL INNER	1			_
69 REAR END PANEL SIDE EXTENSION LH Dected 2 \$ 362.10 \$ 724.20 362.70 70 TAILLAMP LN SMUDIC RH LH Dected 2 \$ 363.40 \$ 726.80 71 TAILLAMP PANEL OUTER LH Dected 2 \$ 544.50 \$ 1,089.00 \$ 544.50 72 TAILLAMP PANEL INNER LH Dected 2 \$ 391.40 \$ 782.80 73 TAILLAMP PANEL INNER LH Dected 2 \$ 391.40 \$ 782.80 73 TAILLAMP LOWER APRON LH Dected 2 \$ 36.10 \$ 172.20 86.70 73 TAILLAMP LOWER APRON RETAINER RH 2 2 \$ 25.10 \$ 50.20 75 TAILLAMP LOWER APRON RETAINER RH 2 2 \$ 25.10 \$ 50.20 75 TAILGATE LOCK To the least of the least	68 REAR END PANEL TOP METAL STRIPE BLA	1			
71 TAILLAMP PANEL OUTER 1 H Detects 2 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 792.50 \$		2	\$ 362.10		17/1/10
71 TAILLAMP PANEL OUTER 14 Detect 2 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ 782.80 \$ 391.40 \$ \$ 2.5 10 \$ 50.20 \$ 2.5 10 \$ 50.20 \$ 2.5 10 \$ 50.20 \$ 2.5 10 \$ 50.20 \$ 2.5 10 \$ 50.20 \$ 2.5 10 \$ 2.5	70 TAILLAMP LIT Smusked, RH ut	2	\$ 363.40	\$ 726.80	
73 TAILLAMP LOWER APRON 4 172.20 74 TAILLAMP LOWER APRON RETAINER 2 \$ 25.10 \$ 50.20 75 TAILGATE 1 \$ 2,051.60 \$ 2,051.60 76 TAILGATE LOCK 1 \$ 398.50 \$ 398.50 77 TAILGATE LOCK ACTUATOR 1 \$ 399.10 \$ 399.10 78 TAILGATE WEATHERSTRIPE 1 \$ 387.30 \$ 387.30 79 TAILGATE INNER TRIM BOARD 1 \$ 165.50 \$ 165.50 80 TAILGATE DAMPER 2 \$ 364.60 \$ 729.10 81 TAILGATE HINGE 2 \$ 76.10 \$ 152.20 82 TAILGATE OUTER GARNISH 1 \$ 236.50 \$ 236.50 83 TAILGATE WIPER MOTOR 1 \$ 69.80 \$ 69.80 84 TAILGATE WIPER MOTOR 1 \$ 485.90 \$ 485.90 85 TAILAGTE WIPER MOTOR COVER 1 \$ 189.60 \$ 189.60 86 TAILGATE TOP REFLECTOR 1 \$ 40.90 \$ 40.90 87 TAILGATE GLASS 1 \$ 1,191.60 \$ 1,191.60 89 TAILGATE GLASS MOULDING 1 \$ 1,250 \$ 172.50 90 TOYOTA LOGO 1 \$ 60.80 \$ 60.80		2			544.00
TAILLAMP LOWER APRON RETAINER TAILLAMP LOCK TAILLAMP LOC	72 TAILLAMP PANEL INNER LH Dested	2	\$ 391.40	\$ 782.80	-391.40
1 \$ 2,051.60 \$ 2,051.60		2	\$ 86.10	\$ 172.20	786-10.
TAILGATE LOCK	74 TAILLAMP LOWER APRON RETAINER WE MAN	2	\$ 25.10	\$ 50.20	× .
76 TAILGATE LOCK 1 \$ 398.50 \$ 398.50 77 TAILGATE LOCK ACTUATOR 1 \$ 399.10 \$ 399.10 78 TAILGATE WEATHERSTRIPE 1 \$ 387.30 \$ 387.30 79 TAILGATE INNER TRIM BOARD 1 \$ 165.50 \$ 165.50 80 TAILGATE DAMPER 2 \$ 364.60 \$ 729.10 81 TAILGATE HINGE 2 \$ 76.10 \$ 152.20 82 TAILGATE OUTER GARNISH 1 \$ 236.50 \$ 236.50 83 TAILGATE GEENER WITH A LAND A LA	75 TAILGATE Orstorted	1	\$ 2,051.60	\$ 2,051.60	
78 TAILGATE WEATHERSTRIPE 1 \$ 387.30 \$ 387.30 79 TAILGATE INNER TRIM BOARD 1 \$ 165.50 \$ 165.50 80 TAILGATE DAMPER 2 \$ 364.60 \$ 729.10 81 TAILGATE HINGE 2 \$ 76.10 \$ 152.20 82 TAILGATE OUTER GARNISH 1 \$ 236.50 \$ 236.50 83 TAILGATE GEENER WING HANDOR 1 \$ 69.80 \$ 69.80 84 TAILGATE WIPER MOTOR 1 \$ 485.90 \$ 485.90 85 TAILAGTE WIPER MOTOR COVER LAD 1 \$ 189.60 \$ 189.60 86 TAILGATE NOZZLE 1 \$ 40.90 \$ 40.90 87 TAILGATE TOP REFLECTOR 1 \$ 87.50 \$ 87.50 88 TAILGATE GLASS MOULDING 1 \$ 1,191.60 \$ 1,191.60 89 TAILGATE GLASS MOULDING 1 \$ 172.50 \$ 172.50 90 TOYOTA LOGO 1 \$ 60.80 \$ 60.80		1			
79 TAILGATE INNER TRIM BOARD 10 1 \$ 165.50 \$ 165		1	\$ 399.10		
1 \$ 165.50		1			7 /
81 TAILGATE HINGE 301.00 5 72.10 82 TAILGATE OUTER GARNISH 301.00 1 \$ 236.50 \$ 236.50 83 TAILGATE GEENER 10.00 10.00 1 \$ 69.80		1		\$ 165.50	
82 TAILGATE OUTER GARNISH 83 TAILGATE GEENER W. W. Fr. W. W. Fr. W. W. Fr. W. W. Fr. W. W. W. Fr. W.		2	\$ 364.60		
\$2 TAILGATE OUTER GARNISH \$236.50 \$236.50 \$3 TAILGATE GENER \$1		2		\$ 152.20	A STATE OF THE PARTY OF THE PAR
84 TAILGATE WIPER MOTOR 1 \$ 485.90 \$ 485.90 85 TAILAGTE WIPER MOTOR COVER 64 1 \$ 189.60 \$ 189.60 86 TAILGATE NOZZLE 1 \$ 40.90 \$ 40.90 87 TAILGATE TOP REFLECTOR 1 \$ 87.50 \$ 87.50 88 TAILGATE GLASS 1 \$ 1,191.60 \$ 1,191.60 89 TAILGATE GLASS MOULDING 1 \$ 172.50 \$ 172.50 90 TOYOTA LOGO 1 \$ 60.80 \$ 60.80		1	\$ 236.50		
84 TAILGATE WIPER MOTOR 1 \$ 485.90 \$ 485.90 85 TAILAGTE WIPER MOTOR COVER LATER AND		1	\$ 69.80	\$ 69.80	~
1 \$ 189.60 \$ 189.60		1	\$ 485.90		
86 TAILGATE NOZZLE 1 \$ 40.90 \$ 40.90 87 TAILGATE TOP REFLECTOR 1 \$ 87.50 \$ 87.50 88 TAILGATE GLASS 1 \$ 1,191.60 \$ 1,191.60 89 TAILGATE GLASS MOULDING 1 \$ 172.50 \$ 172.50 90 TOYOTA LOGO 1 \$ 60.80 \$ 60.80		1	\$ 189.60		4 /
87 TAILGATE TOP REFLECTOR \$87.50 88 TAILGATE GLASS \$1,191.60 89 TAILGATE GLASS MOULDING \$1,791.60 90 TOYOTA LOGO \$15		1	\$ 40.90		- 1 -
88 TAILGATE GLASS \$ 1,191.60 \$ 1,191.60 89 TAILGATE GLASS MOULDING 1 \$ 172.50 \$ 172.50 90 TOYOTA LOGO 1 \$ 60.80 \$ 60.80		1	\$ 87.50	 	-
89 TAILGATE GLASS MOULDING		1	\$ 1,191.60	 	-
90 TOYOTA LOGO		1			-
91 KEAR BODY PANEL LA Greeked 2 \$ 1,718.50 \$ 3,437.00 1718				\$ 60.80	
	STIREAR BODY PANEL LA Brillia	2	\$ 1,718.50	\$ 3,437.00	1718.3

92 REAR BODY PANEL AIR VENT	2	\$ 45.10	\$ 90.20
93 REAR BODY PANEL RAIL GUIDE	2	\$ 518.10	\$ 1,036.40
94 REAR BODY PANEL RAIL GUIDE END PIECE	2	\$ 95.40	\$ 190.80
95 FLOOR PANEL Bucley	1	\$ 2,298.50	\$ 2,298.50
96 REAR EXHAUST PIPE	1	\$ 584.50	\$ 584.50
97 REAR EXHAUST PIPE MOUNTING	1	\$ 34.10	\$ 34.10
98 REAR EXHAUST PIPE GASKET	1	\$ 30.90	\$ 30.90

TOTAL PRICE:
LESS 25%
SUB TOTAL PRI

33431 85

SUB TOTAL PRICE:

\$ 55,895.40

\$ 13,973.85

\$ 41,921.55

SPECIAL NETT ITEMS

ITEMS	QTY		UNIT PRICE	TOTAL
1 FRONT NUMBER PLATE Sent	1	\$	30.00	\$ 30.00
2 FRONT BUMPER CLIPS 7 m/	1 SET	\$	30.00	\$ 30.00
3 FRONT GRILLE CLIPS	1 SET	\$	30.00	\$ 30.00
4 BONNET ADVERTISEMENT STICKER NW	1 SET	\$	380.00	\$ 380.00
5 FRONT SUPPORT PANEL TOP GARNISH CLIPS	1 SET	\$	20.00	\$ 20.00
6 RADIATOR COOLANT	1	\$	40.00	\$ 40.00
7 WIPER PANEL GARNISH CLIPS M	1 SET	\$	30.00	\$ 30.00
8 INTER COOLER COWLING CLIPS New	1 SET	\$	20.00	\$ 20.00
9 FORNT DOOR COMPANY ADDRESS STICKER XWV	1	\$	30.00	\$ 30.00
10 FRONT WINDSCREEN SEALANT M	1	\$	60.00	\$ 60.00
11 ERP BRACKET New	1	\$	25.00	\$ 25.00
12 FIREWALL INSULATION PAD Crupled	1	\$	500.00	\$ -500.00
13 FIREWALL INSULATION PAD CLIPS A	1 SET	\$	50.00	\$ 50.00
14 FRONT SEAT REAR PARTITION PANEL Bed	1	\$	850.00	\$ 850.00
15 REAR NUMBER PLATE BW	1	\$	30.00	\$ 30.00
16 REAR BUMPER CLIPS PE	1 SET	\$	30.00	\$ 30.00
17 REVERSE SENSOR	1 SET	\$	280.00	\$ 280.00
18 REAR END PANEL TOP PLATE RIVETS	1 SET	\$	20.00	\$ 20.00
19 REAR END PANEL SEALANT	1	\$	60.00	\$ 60.00
20 TAILLAMP LOWER APRON CLIPS Num	2 SET	\$	10.00	\$ 20.00
21 TAILGATE OUTER GARNISH CLIPS AN	1 SET	\$	20.00	\$ 20.00
22 TAILAGTE INNER TRIM BOARD CLIPS New	1 SET	\$	30.00	\$ 30.00
23 TAILGATE WIPER MOTOR COVER CLIPS M	1 SET	\$	20.00	\$ 20.00
24 TAILGATE CLASS SEALANT 2	1	\$	60.00	\$ 60.00
25 70 KM/H STOCKER / KW	1	\$	15.00	\$ 15.00
26 8 PAX STICKER	1	\$	15.00	\$ 15.00
27 REAR BODY PANEL ADVERTISEMENT STICKERS AW	2 SET	\$	680.00	\$ 1,360.00
28 FLOOR PANEL TOP MAT TOP	1	\$	650.00	\$ -650.00
29 FLOOR PANEL TOP CLIPS	1 SET	\$	50.00	\$ 50.00
30 FLOOR PANEL TOP BOARD Could	1	\$	800.00	\$ 800.00
31 REAR CABIN CARPENTRY FUNITURE Smushed	1	\$	2,000.00	\$ 2,000.00
16A5		TOTA		\$ 7,555.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS (FRONT)	\$ 2,000.00	1400.	
2	SPRAY PAINTING TO AFFECTED AREA (FRONT)	\$ 1,600.00	12/00	VIII (1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1
3	WIRING CHECK (FRONT)	\$ 100.00	- 35	
4	TO SPRAY TUFF COAT (FRONT)	\$ 200.00	- 120	· · · · · · · · · · · · · · · · · · ·
5	TO REMOVE UPHOLSTERY (FRONT)	\$ -150.00	- 80	
6	TO REMOVE CONDENSER AND TO TOP UP AIR CON GAS	\$ 120.00	-60.	***************************************

8 TO REMOVE AND REFIT RADIATOR 8 TO REMOVE DASHBOARD 9 TO REMOVE FRONT WINDSCREEN 10 TO TRANSFER DOOR FITTINGS 11 TO REMOVE INTERCOOLER 12 TO REMOVE AIR CON BLOWER & EVAPORATOR 13 TO REMOVE AIR CON BLOWER & EVAPORATOR 14 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS 15 TO REMOVE SEAT BELTS 15 TO REPAIR & INNER CABIN PANELS & ENGINE BAY 16 PANEL BEATING, REMOVE AND REFIT PARTS (REAR) 17 SPRAY PAINTING TO AFFECTED AREA (REAR) 18 WIRING CHECK (REAR) 19 TO SPRAY TUFF COAT (REAR) 20 TO REMOVE EVERSE SENSOR 21 TO REMOVE REAR CAMERA 22 TO REMOVE REAR CAMERA 3 100:00 5 100 6 20 7 TO REMOVE REAR CAMERA 5 100:00 5 20 7 TO REMOVE REAR CAMERA 5 100:00 5 20 7 TO REMOVE REAR CAMERA 5 100:00 5 20 7 TO REMOVE REAR CAMERA 5 100:00 5 20 7 TO REMOVE REAR CAMERA 5 100:00 5 20 7 TO REMOVE REAR CAMERA 5 100:00 5 20 7 TO REMOVE REAR CAMERA 7 TO REMOVE REAR CAMERA 8 100:00 7 TO REMOVE REAR CAMERA 9 100:00 10 20 10 3 20 10 TO REMOVE REAR CAMERA 10 10:00 10 20 10 3 20 10 TO REMOVE REAR CAMERA 10 10:00 10 20 20 10 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20 20					,
9 TO REMOVE FRONT WINDSCREEN 10 TO TRANSFER DOOR FITTINGS 11 TO REMOVE INTERCOOLER 12 TO REMOVE AIR CON BLOWER & EVAPORATOR 13 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS 14 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS 15 TO REMOVE SEAT BELTS 16 PANEL BEATING, REMOVE AND REFIT PARTS (REAR) 17 SPRAY PAINTING TO AFFECTED AREA (REAR) 18 WIRING CHECK (REAR) 19 TO SPRAY TUFF COAT (REAR) 20 TO REMOVE REVERSE SENSOR 21 TO REMOVE REVERSE SENSOR 22 TO REMOVE REAR CAMERA 3 100.00 50 23 TO TRANSFER TAILAGTE FITTINGS 3 150.00 60 24 TO REMOVE REAR CABIN CARPENTRY FUNITURE 3 500.00 500 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 3 500.00 500 27 TO REMOVE REAR CABIN CARPENTRY FUNITURE 4 500.00 500 28 500.00 60 29 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 500 20 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 500 27 TO REMOVE REAR EXHAUST PIPE	7	TO REMOVE AND REFIT RADIATOR	\$	120.00	60
9 TO REMOVE FRONT WINDSCREEN 10 TO TRANSFER DOOR FITTINGS 11 TO REMOVE INTERCOOLER 12 TO REMOVE AIR CON BLOWER & EVAPORATOR 13 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS 14 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS 15 TO REPAIR & INNER CABIN PANELS & ENGINE BAY 16 PANEL BEATING, REMOVE AND REFIT PARTS (REAR) 17 SPRAY PAINTING TO AFFECTED AREA (REAR) 18 WIRING CHECK (REAR) 19 TO SPRAY TUFF COAT (REAR) 20 TO REMOVE REVERSE SENSOR 21 TO REMOVE REVERSE SENSOR 22 TO REMOVE REAR CAMERA 31 TO TRANSFER TAILAGTE FITTINGS 32 TO TRANSFER TAILAGTE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR CABIN CARPENTRY FUNITURE 28 150.00 29 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 20 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 20 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 27 TO REMOVE REAR EXHAUST PIPE	8	TO REMOVE DASHBOARD	\$	350.00	700
10 TO TRANSFER DOOR FITTINGS 11 TO REMOVE INTERCOOLER 12 TO REMOVE AIR CON BLOWER & EVAPORATOR 13 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS 14 TO REMOVE SEAT BELTS 15 TO REPAIR & INNER CABIN PANELS & ENGINE BAY 16 PANEL BEATING, REMOVE AND REFIT PARTS (REAR) 17 SPRAY PAINTING TO AFFECTED AREA (REAR) 18 WIRING CHECK (REAR) 19 TO SPRAY TUFF COAT (REAR) 20 TO REMOVE UPHOLSTERY (REAR) 21 TO REMOVE REVERSE SENSOR 22 TO REMOVE REVERSE SENSOR 23 TO TRANSFER TAILAGTE FITTINGS 24 TO REPLACE TAILGATE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR CABIN CARPENTRY FUNITURE 28 500.00 29 TO REMOVE REAR CABIN CARPENTRY FUNITURE 20 TO REMOVE REAR EXHAUST PIPE 5 150.00 20 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 27 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 28 500.00 29 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 20 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 20 TO REMOVE REAR EXHAUST PIPE	9	TO REMOVE FRONT WINDSCREEN	\$		
12 TO REMOVE AIR CON BLOWER & EVAPORATOR 13 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS 14 TO REMOVE SEAT BELTS 15 TO REPAIR & INNER CABIN PANELS & ENGINE BAY 16 PANEL BEATING, REMOVE AND REFIT PARTS (REAR) 17 SPRAY PAINTING TO AFFECTED AREA (REAR) 18 WIRING CHECK (REAR) 19 TO SPRAY TUFF COAT (REAR) 20 TO REMOVE UPHOLSTERY (REAR) 21 TO REMOVE REVERSE SENSOR 22 TO REMOVE REAR CAMERA 3 TO TRANSFER TAILAGTE FITTINGS 3 TO TRANSFER TAILAGTE FITTINGS 4 TO REPLACE TAILGATE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR CABIN CARPENTRY FUNITURE 28 TO REMOVE REAR CABIN CARPENTRY FUNITURE 29 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 20 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 27 TO REMOVE REAR CABIN CARPENTRY FUNITURE 5 500.00 28 TO REMOVE REAR EXHAUST PIPE 5 150.00			\$	300.00	
13 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS \$ 500.00 \$ 35.00 14 TO REMOVE SEAT BELTS \$ 150.00 \$ 10.00 15 TO REPAIR & INNER CABIN PANELS & ENGINE BAY \$ 500.00 \$ 16.00 16 PANEL BEATING, REMOVE AND REFIT PARTS (REAR) \$ 2,000.00 \$ 16.00 17 SPRAY PAINTING TO AFFECTED AREA (REAR) \$ 2,000.00 \$ 140.00 18 WIRING CHECK (REAR) \$ 100.00 \$ 3.00 19 TO SPRAY TUFF COAT (REAR) \$ 280.00 \$ 1.20 20 TO REMOVE UPHOLSTERY (REAR) \$ 250.00 \$ 1.00 21 TO REMOVE REVERSE SENSOR \$ 100.00 \$ 5.00 22 TO REMOVE REAR CAMERA \$ 100.00 \$ 5.00 23 TO TRANSFER TAILAGTE FITTINGS \$ 150.00 \$ 6.00 24 TO REPLACE TAILGATE GLASS \$ 80.00 \$ 6.00 25 TO VACCUM GLASS FRAGMENTS \$ 80.00 \$ 6.00 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE \$ 500.00 \$ 2.00 27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 \$ \$	11	TO REMOVE INTERCOOLER	\$	100.00	50
13 TO REMOVE AIR BAGS & TO RESET AIR BAG SETTINGS \$ 500.00 3.5 3.1 14 TO REMOVE SEAT BELTS \$ 150.00 10.3 3.1 15 TO REPAIR & INNER CABIN PANELS & ENGINE BAY \$ 500.00 40.3 3.1 16 PANEL BEATING, REMOVE AND REFIT PARTS (REAR) \$ -2,600.00 16.0 0.1 17 SPRAY PAINTING TO AFFECTED AREA (REAR) \$ -2,000.00 140.0 18 WIRING CHECK (REAR) \$ 100.00 3.0 19 TO SPRAY TUFF COAT (REAR) \$ 200.00 12.0 0.1 20 TO REMOVE UPHOLSTERY (REAR) \$ -250.00 12.0 0.1 21 TO REMOVE REVERSE SENSOR \$ 100.00 5.0 22 TO REMOVE REAR CAMERA \$ 100.00 5.0 23 TO TRANSFER TAILAGTE FITTINGS \$ 150.00 6.0 24 TO REPLACE TAILAGTE GLASS \$ 150.00 6.0 25 TO VACCUM GLASS FRAGMENTS \$ 80.00 6.0 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE \$ 500.00 2.0 0.0 27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 ×	12	TO REMOVE AIR CON BLOWER & EVAPORATOR	\$	300.00	266
15 TO REPAIR & INNER CABIN PANELS & ENGINE BAY \$ 500.00 \$ 20.00 \$ 16.00 \$ 17.0			\$		
16 PANEL BEATING, REMOVE AND REFIT PARTS (REAR) 17 SPRAY PAINTING TO AFFECTED AREA (REAR) 18 WIRING CHECK (REAR) 19 TO SPRAY TUFF COAT (REAR) 20 TO REMOVE UPHOLSTERY (REAR) 21 TO REMOVE REVERSE SENSOR 22 TO REMOVE REVERSE SENSOR 23 TO TRANSFER TAILAGTE FITTINGS 24 TO REPLACE TAILAGTE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR EXHAUST PIPE 3 150.00 4 1600 5 2,000.00 1 400 1 200 1 400	14	TO REMOVE SEAT BELTS	\$	150.00	- 100
17 SPRAY PAINTING TO AFFECTED AREA (REAR) 18 WIRING CHECK (REAR) 19 TO SPRAY TUFF COAT (REAR) 20 TO REMOVE UPHOLSTERY (REAR) 21 TO REMOVE REVERSE SENSOR 22 TO REMOVE REAR CAMERA 23 TO TRANSFER TAILAGTE FITTINGS 24 TO REPLACE TAILGATE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$			\$	500.00	400
18 WIRING CHECK (REAR) 19 TO SPRAY TUFF COAT (REAR) 20 TO REMOVE UPHOLSTERY (REAR) 21 TO REMOVE REVERSE SENSOR 22 TO REMOVE REAR CAMERA 23 TO TRANSFER TAILAGTE FITTINGS 24 TO REPLACE TAILGATE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$			\$	-2,600.00	1600
18 WIRING CHECK (REAR) \$ 100.00 3 0 19 TO SPRAY TUFF COAT (REAR) \$ 280.00 120 20 TO REMOVE UPHOLSTERY (REAR) \$ -250.00 120 21 TO REMOVE REVERSE SENSOR \$ 100.00 50 22 TO REMOVE REAR CAMERA \$ 100.00 50 23 TO TRANSFER TAILAGTE FITTINGS \$ 150.00 6 0 24 TO REPLACE TAILGATE GLASS \$ 5990.00 120 25 TO VACCUM GLASS FRAGMENTS \$ 80.00 6 0 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE \$ 500.00 200 27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 X	17	SPRAY PAINTING TO AFFECTED AREA (REAR)	\$	2,000.00	1400
20 TO REMOVE UPHOLSTERY (REAR) 21 TO REMOVE REVERSE SENSOR 22 TO REMOVE REAR CAMERA 23 TO TRANSFER TAILAGTE FITTINGS 24 TO REPLACE TAILGATE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 ×			\$		
21 TO REMOVE REVERSE SENSOR \$ 100.00	19	TO SPRAY TUFF COAT (REAR)	\$	280.00	- 120
22 TO REMOVE REAR CAMERA \$ 100.00	20	TO REMOVE UPHOLSTERY (REAR)	\$	-250.00	120.
22 TO REMOVE REAR CAMERA 23 TO TRANSFER TAILAGTE FITTINGS 24 TO REPLACE TAILGATE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 ×	21	TO REMOVE REVERSE SENSOR	\$	·100.00	- 50
24 TO REPLACE TAILGATE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR EXHAUST PIPE 3 150.00 ×	22	TO REMOVE REAR CAMERA	\$	100.00	
24 TO REPLACE TAILGATE GLASS 25 TO VACCUM GLASS FRAGMENTS 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE 27 TO REMOVE REAR EXHAUST PIPE 30 TO VACCUM GLASS FRAGMENTS 500.00 20 TO VACCUM GLASS FRAGMENTS 500.00 20 TO VACCUM GLASS FRAGMENTS 5 80.00 20 TO VACCUM GLASS FRAGMENTS	23	TO TRANSFER TAILAGTE FITTINGS	\$	150:00	- 60
25 TO VACCUM GLASS FRAGMENTS \$ 80.00 60 26 TO REMOVE REAR CABIN CARPENTRY FUNITURE \$ 500.00 300 27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 ×	24	TO REPLACE TAILGATE GLASS	\$		
26 TO REMOVE REAR CABIN CARPENTRY FUNITURE \$ 500.00 \$0.00 \$150	25	TO VACCUM GLASS FRAGMENTS	\$		- 60
27 TO REMOVE REAR EXHAUST PIPE \$ 150.00 ×			\$	500.00	
28 TOWING FEES \$ 60.00	27	TO REMOVE REAR EXHAUST PIPE	-		
	28	TOWING FEES	\$	60.00	

TOTAL:

\$ 14,840.00

8440

ESTIMATE REPORT

TOTAL PARTS COST:

5

49,476.55

TOTAL LABOUR COST:

\$ 14,840.00

TOTAL REPAIR COST:

\$ 64,316.55

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

FAX:

told: 46906.85 1/s: 37.5k.

30 Days

375K

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: