## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No.: SHC3216P

Make : HYUNDAI

Model : IONIQ Date: 13/01/2023

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount	
	1 REAR BUMPER COVER			Sc = \$459.40	
	10 REAR BUMPER CLIPS			WEC \$22.00	
	1 REAR BUMPER CENTRE MOULDING ASSY			907 \$451.25	
	1 REAR BUMPER REINFORCEMENT			2 \$394.80	1
	1 REAR BUMPER REINFORCEMENT BRACKET RH		THE PARTY OF THE P	7, \$138.10	1
	1 ANTENNA SMARTKEY			? \$40.50	1
	1 REAR BUMPER FOG LAMP			7, \$201.50	1
	1 BOOTLID HYUNDAI PLATE			MG \$24.30	1
	1 EMBLEM HYBRID			\$24.30	1
	1 EMBLEM - IONIQ			\$31.30	1
	SUB TOTAL			\$1,787.45	1
	LESS 25%	Awi Arraino		\$446.86	1
	DISCOUNTED TOTAL			\$1,340.59	1
	BOOTLID COMFORT TEL NO STICKER			\$40.00	+
	BOOTLID COMFORT LOGO.STICKER			\$30.00	1
	BOOTLID COMFORT APP STICKER			\$30.00	L
	REAR NUMBER PLATE WITH TRIM COVER			( ° \$55.00	
	REAR BUMPER REVERSE SENSOR		TATION PRODUTE	? \$180.00	ŀ
	REAR BUMPER RUBBER MAT			NC\$50.00	
			NETT	\$285.00	ľ
	Labour Charge				
	PANEL BEATING			\$400.00	
	SPRAY PAINTING CHARGE			\$600.00	
	REMOVE/REFIX REVERSE SENSOR			7, \$80.00	F
	TOTAL LABOUR			\$1,080.00	P
	ESTIMATE TOTAL			\$2,705.59	
	pairer of the following:			1497.52	
e PRA-	ital Setimbted based complifyricus line paction of the shove vehicle. The	na final ra	nair auantum will h	6: 299.50	
the Do	pairer of the following:			= 1198.02.	

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: