

Vehicle Damage Assessment Report for [SLB2671Y]

Estimate Created: 02/02/2023 14:02 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 15/05/2023 15:24 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Volkswagen	Model	Golf
Engine Type			
License Plate Number	SLB2671Y	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$7,900.00 WITH 6 WORKING
DAYS

Insurlogic 4 (15/05/2023 15:22)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER		1	1098.00	-10.00 %	988.20
FRONT BUMPER GRILLE		1	476.35	-10.00 %	428.72
FRONT BUMPER GRILLE LOGO		1	155.20	-10.00 %	139.68
FRONT BUMPER REINFORCEMENT SPONGE		1	231.75	-10.00 %	208.58
FRONT FENDER LH		1	694.33	-10.00 %	624.90
HEADLAMP		2	1568.75	-10.00 %	2,823.75
BONNET		1	1380.00	-10.00 %	1,242.00
BONNET HINGE		2	183.40	-10.00 %	330.12
BONNET BOTTOM LOCK		1	302.88	-10.00 %	272.59
FRONT BRACE PANEL		1	135.55	-10.00 %	122.00
FRONT SUPPORT PANEL		1	1048.00	-10.00 %	943.20
FRONT SUPPORT PANEL CENTER BEAM		1	199.87	-10.00 %	179.88

Parts Subtotal 8,303.62

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT NUMBER PLATE		1.0	60.00	0.00 %	60.00
SET FRONT BUMPER CLIPS		1.0	30.00	0.00 %	30.00
SET FRONT GRILLE CLIP (UPPER)		1.0	20.00	0.00 %	20.00
COOLANT		1.0	40.00	0.00 %	40.00

Materials Subtotal 150.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
PANEL BEATING	RnR	800.00	0.00 %	800.00
REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	RnR	60.00	0.00 %	60.00
REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	RnR	60.00	0.00 %	60.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
SPRAY PAINTING	Full spray	600.00	0.00 %	600.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	920.00
			Paint Labor Subtotal	600.00
			Labor Subtotal	1,520.00

Summary

Repair Cost	9,973.62
Discount(20 %)	(1,994.72)
	7,978.90
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	7,978.90