

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST015/23/TP

Your Ref: TP claim against GBJ7250Y

20-Feb-23

Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Hyundai i30 Wagon no: SBV3311T

Date of accident: 16-01-2023

Parts supply (Nett)

1 pc Rear R/h door *Perked.*
1 pc Rear R/h door outer handle *new*
1 pc Rear R/h door outer moulding *new*
2 pcs Rear R/h door hinges @\$75.00 *new*
1 pc Rear R/h door weatherstrip *new*
1 set Rear R/h door black tape *all*
1 pc Rear R/h door inner lock *new*
1 pc Rear R/h door regulator *new*
1 pc Rear R/h door regulator motor *new*
1 pc Rear R/h door sensor *new*
1 pc Rear R/h door check *new*
1 pc Rear R/h door inner board *new*
1 pc Front R/h door outer handle *new*

3603
less 20% : 2882.40

1,918.00 ✓
85.00 +
145.00 +
150.00 +
230.00 ✓
110.00 ✓
280.00 ✓
385.00 ✓
289.00 +
165.00 +
65.00 +
680.00 ✓
85.00 +

4,587.00

Less 10%: (458.70)

20% 550.00 300

9/10 750.00 500
80.00 ✓
30.00 ✓

SS 5,538.30

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove and refit door glass to facilitate repair

To check wirings.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L;
H/S 20/02/23

04 Days

Total: 3792.40

H/S 3K.