



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 396G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	STICKER STRIDES TAXI (DOOR) (SN)	NECESSARY	60.00	60.00
1	WEATHERSTRIP, REAR DOOR, NO.2, RH	NOT NECESSARY	39.10	-
1	PANEL SUB-ASSY, FRONT DOOR RH	TO REPAIR SEE LABOUR	1,407.80	-
1	DOOR OUTER HANDLE FRONT, RH	TO REPAIR SEE LABOUR	423.20	-
1	COVER, OUTER MIRROR, RH	TO REPAIR SEE LABOUR	117.80	-
1	PANEL SUB-ASSY, REAR DOOR, RH	TO REPAIR SEE LABOUR	1,401.70	-
1	DOOR OUTER HANDLE REAR, RH	TO REPAIR SEE LABOUR	105.50	-
1	MOULDING ASSY, BODY ROCKER PANEL, RH	TO REPAIR SEE LABOUR	584.80	-
1	PANEL SUB-ASSY, FENDER REAR RH	TO REPAIR SEE LABOUR	943.10	-
1	WHEEL, DISC	TO REPAIR SEE LABOUR	2,036.30	-
			7,119.30	60.00
LABOUR				
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, FRONT DOOR RH, DOOR OUTER HANDLE FRONT, RH, COVER, OUTER MIRROR, RH, PANEL SUB-ASSY, REAR DOOR, RH, DOOR OUTER HANDLE REAR, RH, MOULDING ASSY, BODY ROCKER PANEL, RH, PANEL SUB-ASSY, FENDER REAR RH AND WHEEL, DISC.		676.00	400.00
	SPRAY PAINT.		2,034.00	890.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	240.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-

Report Ref No. NS/INC23001129/Gqy3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			3,430.00	1,370.00
GRAND TOTAL			10,549.30	1,430.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,150.00

Report Ref No. NS/INC23001129/Gqy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.