



Case Details

Case Reference Number : TAX/11/22/2045
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF396G

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19898-ID
 Assigned By : Wei Siong #

Insurance Company Name : income insurance limited
 Accident Date and Time : 21/11/2022 03:55 AM
 Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,407.80	1,407.80	30.00	985.46	Replace	1	0	Repair	X Repair
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	ABC
One Time Key In	Main			DOOR OUTER HANDLE FRONT , RH	1	423.20	423.20	25.00	317.40	Replace	1	0	Repair	X
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	117.80	117.80	25.00	88.35	Replace	1	0	Repair	X
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,401.70	1,401.70	25.00	1,051.28	Replace	1	0	Repair	X
One Time Key In	Main			WEATHERSTRIP, REAR DOOR , NO.2 , RH	1	39.10	39.10	25.00	29.33	Replace	0	0	Not Give	X
One Time Key In	Main			DOOR OUTER HANDLE REAR , RH	1	105.50	105.50	25.00	79.13	Replace	1	0	Repair	X
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	584.80	584.80	25.00	438.60	Replace	1	0	Repair	X
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	943.10	943.10	25.00	707.33	Replace	1	0	Repair	X
Standard	Main			WHEEL, DISC	1	2,036.30	2,036.30	25.00	1,527.23	Replace	1	0	Repair	X
Total Spare Part Cost									5,284.11			Surveyor Total	60.00	
Lump Sum Discount (%)									20.00			Lump Sum Dis (%)	20	
Final Spare Part Cost									4,227.29			Final Sur Total	48.00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			676.00	400.00	

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Other	720.00	80.00
Overall Total	7,657.29	1,418.00
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	7,650.00	1,400.00
Surveyor Approved Amount		1,400.00
No of Repair Days*	6	4
Remarks	-	LUMPSUM REPAIR / AFTER PAINT PHOTOS FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR NUMBER 87471175 Send pictures@lkk.com.sg 87882222
Surveyor Name		GuoQiang
Signature		
Survey Date	23/11/2022	

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts photo for repair confirmation
- To repair on "Without Prejudice" basis
- No cash payment allowed
- Stop work until resurveyed and is subject to approval from insurance Company

Acknowledged by Repairer
Signature:
Date: