



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/11/2022

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SHF396G
Case Reference Number	TAX/11/22/2045
Registration Date	17/12/2019
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	TAN ANN KAH
Type of Accident	Side Swipe
Accident Date and Time	21/11/2022 11:55 AM
Accident Reported Date and Time	22/11/2022 11:31 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116933
Special Instruction to ARC,if any	RIGHT SIDE/TP / INCOME - LKK
Prepared Date and Time	22/11/2022 3:06 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$2,034.00	\$890.00
Total Spare Part Cost	\$4,227.29	\$48.00
Total Other Cost	\$720.00	\$80.00
TOTAL COST	\$7,657.29	\$1,418.00
Lump Sum Total	\$7,650.00	\$1,400.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Boon Chew Tay	GuoQiang
ARC / Surveyor Sign Off Date	23/11/2022 1:59 PM	23/11/2022 12:00 PM
Signature		
Remarks		LUMPSUM REPAIR / AFTER PAINT PHOTOS ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quoqiang (LKK) & Email :guoqiang@lkkauto.com HP:82880282

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/11/2022

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY DOOR HANDLE	\$360.00	\$60.00
RESPRAY MIRROR COVER RH	\$180.00	\$50.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$2,034.00	\$890.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$720.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		69210-47041-A1	DOOR OUTER HANDLE FRONT , RH	1.00	\$423.20	100.00	\$0.00	Replace	Repair
		87915-47070-A1	COVER, OUTER MIRROR, RH	1.00	\$117.80	100.00	\$0.00	Replace	Repair
		67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair
		6789547010	WEATHERSTRIP, REAR DOOR , NO.2 , RH	0.00	\$39.10	0.00	\$0.00	Replace	Not Given
		69211-47021-A1	DOOR OUTER HANDLE REAR , RH	1.00	\$105.50	100.00	\$0.00	Replace	Repair
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$584.80	100.00	\$0.00	Replace	Repair
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	100.00	\$0.00	Replace	Repair
		4261147450	WHEEL, DISC	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair
Total					\$7,119.30		\$60.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									