

2/2/23, 3:46 PM

## Repairer Estimates



Main Office : No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 6891

Service Centre : Block 100B, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

Mova Spray Centre  
2K Oven Spray Painting System

Power-M Automotive Pte Ltd  
Specialise In Car Air-con Services,  
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

ERGO Insurance Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

|                               |                        |                       |                   |
|-------------------------------|------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)        | Ref. No:              |                   |
| Policy No:                    | DMPG22010587           | Date of Loss:         | 31/01/2023        |
| Vehicle Reg. No.:             | SJV9910E               | Driveable?            |                   |
| Driver Age/Info:              |                        | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                     | Third Party Involved? | YES               |
| Insured/Claimant:             | LOO CHERN LIANG        |                       |                   |
| Make/Model:                   | TOYOTA VIOS E, 1.5 (A) | Vehicle Reg. Date:    | 26/02/2010        |
| Vehicle Colour:               | SILVER                 |                       |                   |
| Engine No:                    | 1NZY036071             | Chassis No:           | MR053HY9305149960 |
| Odometer:                     | 0 KM                   |                       |                   |
| Paint Type:                   |                        |                       |                   |
| Total Loss?                   | NO                     |                       |                   |
| Est. Duration of Repair (day) | 10                     |                       |                   |

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

**COST OF CLAIMS**

|                         | Amount           |
|-------------------------|------------------|
| Parts                   | 8,247.00         |
| Miscellaneous Items     | 0.00             |
| Labour                  | 2,450.00         |
| Paintwork Labour        | 0.00             |
| Towing                  | 0.00             |
| <b>Gross Total (\$)</b> | <b>10,697.00</b> |
| <b>+ GST 8.00% (\$)</b> | <b>855.76</b>    |
| <b>Nett Amount (\$)</b> | <b>11,552.76</b> |

This claim is handled by: ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## AIR DETAILS

## Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2023)  
 Parts: 143 TOYOTA VIOS E 1.5 (A) (Catalogue: Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Mova Automotive Pte Ltd/SJV9910E/02/02/2023 15:46  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                                      | %Disc | %Depr | Amount              |
|-----|-----|----------|--------------------------------------------------|-------|-------|---------------------|
| 1   | 1   |          | *FRONT BONNET <i>bu</i>                          | 0.00  | 0.00  | *420.00 F           |
| 2   | 1   |          | *FRONT BONNET HINGE LH <i>bt</i>                 | 0.00  | 0.00  | *62.00 F            |
| 3   | 1   |          | *FRONT BONNET HINGE RH <i>bt</i>                 | 0.00  | 0.00  | *62.00 F            |
| 4   | 1   |          | *FRONT BONNET LOCK <i>bt</i>                     | 0.00  | 0.00  | *95.00 F            |
| 5   | 1   |          | *FRONT GRILLE <i>cm</i>                          | 0.00  | 0.00  | *185.00 F           |
| 6   | 1   |          | *FRONT GRILLE EMBLEM <i>cm</i>                   | 0.00  | 0.00  | *72.00 F            |
| 7   | 1   |          | *FRONT GRILLE MOULDING <i>cm</i>                 | 0.00  | 0.00  | *110.00 F           |
| 8   | 1   |          | *FRONT GRILLE INNER RETAINER GUIDE               | 0.00  | 0.00  | *160.00 F           |
| 9   | 1   |          | *FRONT BUMPER <i>cm</i>                          | 0.00  | 0.00  | *280.00 F           |
| 10  | 1   |          | *FRONT BUMPER REINFORCEMENT <i>bt</i>            | 0.00  | 0.00  | *275.00 F           |
| 11  | 1   |          | *FRONT BUMPER TOWING COVER <i>mi</i>             | 0.00  | 0.00  | *32.00 F            |
| 12  | 1   |          | *FRONT BUMPER LOWER GRILLE <i>de</i>             | 0.00  | 0.00  | *110.00 F           |
| 13  | 1   |          | *FRONT BUMPER SIDE RETAINER LH <i>re</i>         | 0.00  | 0.00  | *75.00 F            |
| 14  | 1   |          | *FRONT BUMPER SIDE RETAINER RH <i>re</i>         | 0.00  | 0.00  | *75.00 F            |
| 15  | 1   |          | *FRONT BUMPER CLIPS <i>re</i>                    | 0     | 0.00  | *40.00 FS <i>30</i> |
| 16  | 1   |          | *FRONT NUMBER PLATE <i>bt</i>                    | 0     | 0.00  | *30.00 FS <i>35</i> |
| 17  | 1   |          | *FRONT NUMBER PLATE HOLDER                       | 0     | 0.00  | *20.00 FS           |
| 18  | 1   |          | *FRONT HORN <i>re</i>                            | 0.00  | 0.00  | *145.00 F           |
| 19  | 1   |          | *FRONT SUPPORT PANEL <i>bt</i>                   | 0.00  | 0.00  | *420.00 F           |
| 20  | 1   |          | *FRONT HEADLAMP LH <i>cm</i>                     | 0.00  | 0.00  | *260.00 F           |
| 21  | 1   |          | *FRONT HEADLAMP RH <i>cm</i>                     | 0.00  | 0.00  | *260.00 F           |
| 22  | 1   |          | *FRONT HEADLAMP UPPER PANEL LH <i>bt</i>         | 0.00  | 0.00  | *120.00 F           |
| 23  | 1   |          | *FRONT HEADLAMP UPPER PANEL RH <i>bt</i>         | 0.00  | 0.00  | *120.00 F           |
| 24  | 1   |          | *FRONT A/COND CONDENSOR <i>bt</i>                | 0.00  | 0.00  | *650.00 F           |
| 25  | 1   |          | *FRONT A/COND LIQUID PIPE                        | 0.00  | 0.00  | *320.00 F           |
| 26  | 1   |          | *FRONT A/COND PRESSURE PIPE                      | 0.00  | 0.00  | *340.00 F           |
| 27  | 1   |          | *FRONT RADIATOR <i>bt</i>                        | 0.00  | 0.00  | *750.00 F           |
| 28  | 1   |          | *FRONT RADIATOR COOLANT <i>re</i>                | 0     | 0.00  | *50.00 FS           |
| 29  | 1   |          | *FRONT RADIATOR FAN GUARD                        | 0.00  | 0.00  | *220.00 F           |
| 30  | 1   |          | *FRONT RADIATOR FAN ASSY                         | 0.00  | 0.00  | *180.00 F           |
| 31  | 1   |          | *FRONT RADIATOR TOP HOSE                         | 0.00  | 0.00  | *42.00 F            |
| 32  | 1   |          | *FRONT RADIATOR TOP HOSE CONNECTOR               | 0.00  | 0.00  | *68.00 F            |
| 33  | 1   |          | *FRONT INLET MANIFOLD                            | 0.00  | 0.00  | *380.00 F           |
| 34  | 1   |          | *FRONT WIPER TANK <i>de</i>                      | 0.00  | 0.00  | *78.00 F            |
| 35  | 1   |          | *FRONT AIR CLEANER ASSY                          | 0.00  | 0.00  | *390.00 F           |
| 36  | 1   |          | *FRONT AIR CLEANER DUCT                          | 0.00  | 0.00  | *92.00 F            |
| 37  | 1   |          | *FRONT FENDER RH <i>bt</i>                       | 0.00  | 0.00  | *240.00 F           |
| 38  | 1   |          | *FRONT WIPER AIR GRILLE <i>cat</i>               | 0.00  | 0.00  | *220.00 F           |
| 39  | 1   |          | *FRONT WIPER AIR GRILLE SIDE COVER RH <i>cat</i> | 0.00  | 0.00  | *62.00 F            |
| 40  | 1   |          | *FRONT FENDER LH - REPAIR                        | 0.00  | 0.00  | -                   |
| 41  | 1   |          | *FRONT WHEEL HOUSE CHASSIS LH/RH - REPAIR        | 0.00  | 0.00  | -                   |

F=Franchise part. S=SpcNett.

|                                     |                 |
|-------------------------------------|-----------------|
| Sub Total (\$\$)                    | 7,510.00        |
| + Margin on L,N Items 10.00% (\$\$) | 737.00          |
| <b>Total Parts (\$\$)</b>           | <b>8,247.00</b> |

Mova Automotive Pte Ltd/SJV9910E/02/02/2023 15:46. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

46 PM

Repairer Estimates

## Estimates on Miscellaneous Items

are no new miscellaneous items selected.

## Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

|                          |                                                                                                                                                                                                                    |     |                          |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--------------------------|
| 1                        | TO REMOVE, REPLACE & REFIT FRONT RADIATOR, RADIATOR FAN ASSY, AIR COND CONDENSOR, AIR COND PIPE & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL & ETC.                                                             | New | 120.00 <del>100</del>    |
| 2                        | TO REMOVE, REPLACE INLET MANIFOLD, AIR CLEANER ASSY, BATTERY & ETC. BACK TO ORIGINAL OPERATIONS                                                                                                                    | New | 100.00 <del>60</del>     |
| 3                        | TO REMOVE, RPELACE, REPAIR, READJUST & CHISEL FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH, FRONT WHEEL HOUSE CHASSIS LH&RH & ETC. BACK TO ORIGINAL CONDITIONS | New | 850.00 <del>800</del>    |
| 4                        | TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH & CHASSIS MEMBER LH&RH                                                                               | New | 1,200.00 <del>1000</del> |
| 5                        | TO CHECK WIRING & ELECTRICAL SYSTEM                                                                                                                                                                                | New | 80.00 <del>30</del>      |
| 6                        | TO REFILL AIR COND GAS & VACUUM                                                                                                                                                                                    | New | 100.00                   |
| Gross Labour Cost (\$\$) |                                                                                                                                                                                                                    |     | 2,450.00                 |

Mova Automotive Pte Ltd/SJV9910E/02/02/2023 15:46. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Ram*  
 Hp 90010068  
 7 days  
 L/S  
 03/02/23 @ 1420  
 EXCESS: 500  
 REVERT  
 Resurvey after repair