

(08/11/13) Web
ASS. REC. BY: Paul

REF: CS/eh/23001133/Ruy3

0458

C06 - 2030/FEB

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJV 99106
at Workshop m/s MOVA
of FOR YOUNG
Insured: ES1
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 500
(Client's Record)
Make of Veh: _____

Veh No: SJV 99106 Yr Regn: 2010 FEB
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: TOYOTA VIUS AUTO C.C. 1497
Colour: GREEN A/C: Insured / Std / NI / NA
Sp. Reading: 395 NA T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MRO53449305149960
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 195/55R15
R: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Bal. or Market Value: 57K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 31/01/23 D.O.I. 03/02/23
Survey held at MOVA
Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR UMTT - 33K</u>

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

1) _____
Date/Time, File Return to? _____
2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS, SI
Photos
Others

Report Format : _____
Lump Sum / I.B.I. (\$) _____

2/2/23, 3:46 PM

Repairer Estimates



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 6891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG22010587	Date of Loss:	31/01/2023
Vehicle Reg. No.:	SJV9910E	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOO CHERN LIANG		
Make/Model:	TOYOTA VIOS E, 1.5 (A)	Vehicle Reg. Date:	26/02/2010
Vehicle Colour:	SILVER	Chassis No:	MR053HY9305149960
Engine No:	1NZY036071		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS

	Amount
Parts	8,247.00
Miscellaneous Items	0.00
Labour	2,450.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	10,697.00
+ GST 8.00% (\$\$)	855.76
Nett Amount (\$\$)	11,552.76

This claim is handled by: ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2023)
 Parts: 143 TOYOTA VIOS E 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Mova Automotive Pte Ltd/SJV9910E/02/02/2023 15:46
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>bt</i>	0.00	0.00	*420.00 F
2	1		*FRONT BONNET HINGE LH <i>bt</i>	0.00	0.00	*62.00 F
3	1		*FRONT BONNET HINGE RH <i>bt</i>	0.00	0.00	*62.00 F
4	1		*FRONT BONNET LOCK <i>bt</i>	0.00	0.00	*95.00 F
5	1		*FRONT GRILLE <i>cm</i>	0.00	0.00	*185.00 F
6	1		*FRONT GRILLE EMBLEM <i>cm</i>	0.00	0.00	*72.00 F
7	1		*FRONT GRILLE MOULDING <i>cm</i>	0.00	0.00	*110.00 F
8	1		*FRONT GRILLE INNER RETAINER GUIDE	0.00	0.00	*160.00 F
9	1		*FRONT BUMPER <i>cm</i>	0.00	0.00	*280.00 F
10	1		*FRONT BUMPER REINFORCEMENT <i>bt</i>	0.00	0.00	*275.00 F
11	1		*FRONT BUMPER TOWING COVER <i>mi</i>	0.00	0.00	*32.00 F
12	1		*FRONT BUMPER LOWER GRILLE <i>de</i>	0.00	0.00	*110.00 F
13	1		*FRONT BUMPER SIDE RETAINER LH <i>ne</i>	0.00	0.00	*75.00 F
14	1		*FRONT BUMPER SIDE RETAINER RH <i>ne</i>	0.00	0.00	*75.00 F
15	1		*FRONT BUMPER CLIPS <i>ne</i>	0	0.00	*40.00 FS <i>30</i>
16	1		*FRONT NUMBER PLATE <i>bt</i>	0	0.00	*30.00 FS <i>35</i>
17	1		*FRONT NUMBER PLATE HOLDER	0	0.00	*28.00 FS
18	1		*FRONT HORN <i>ne</i>	0.00	0.00	*145.00 F
19	1		*FRONT SUPPORT PANEL <i>bt</i>	0.00	0.00	*420.00 F
20	1		*FRONT HEADLAMP LH <i>cm</i>	0.00	0.00	*260.00 F
21	1		*FRONT HEADLAMP RH <i>cm</i>	0.00	0.00	*260.00 F
22	1		*FRONT HEADLAMP UPPER PANEL LH <i>bt</i>	0.00	0.00	*120.00 F
23	1		*FRONT HEADLAMP UPPER PANEL RH <i>bt</i>	0.00	0.00	*120.00 F
24	1		*FRONT A/COND CONDENSOR <i>bt</i>	0.00	0.00	*650.00 F
25	1		*FRONT A/COND LIQUID PIPE <i>?</i>	0.00	0.00	*320.00 F
26	1		*FRONT A/COND PRESSURE PIPE <i>?</i>	0.00	0.00	*340.00 F
27	1		*FRONT RADIATOR <i>bt</i>	0.00	0.00	*750.00 F
28	1		*FRONT RADIATOR COOLANT <i>ne</i>	0	0.00	*50.00 FS
29	1		*FRONT RADIATOR FAN GUARD <i>?</i>	0.00	0.00	*220.00 F
30	1		*FRONT RADIATOR FAN ASSY <i>?</i>	0.00	0.00	*180.00 F
31	1		*FRONT RADIATOR TOP HOSE <i>?</i>	0.00	0.00	*42.00 F
32	1		*FRONT RADIATOR TOP HOSE CONNECTOR <i>?</i>	0.00	0.00	*68.00 F
33	1		*FRONT INLET MANIFOLD <i>?</i>	0.00	0.00	*380.00 F
34	1		*FRONT WIPER TANK <i>de</i>	0.00	0.00	*78.00 F
35	1		*FRONT AIR CLEANER ASSY <i>?</i>	0.00	0.00	*390.00 F
36	1		*FRONT AIR CLEANER DUCT <i>?</i>	0.00	0.00	*92.00 F
37	1		*FRONT FENDER RH <i>bt</i>	0.00	0.00	*240.00 F
38	1		*FRONT WIPER AIR GRILLE <i>cad</i>	0.00	0.00	*220.00 F
39	1		*FRONT WIPER AIR GRILLE SIDE COVER RH <i>cat</i>	0.00	0.00	*62.00 F
40	1		*FRONT FENDER LH - REPAIR	0.00	0.00	-
41	1		*FRONT WHEEL HOUSE CHASSIS LH/RH - REPAIR	0.00	0.00	-

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	7,510.00
+ Margin on L,N Items 10.00% (\$\$)	737.00
Total Parts (\$\$)	8,247.00

Mova Automotive Pte Ltd/SJV9910E/02/02/2023 15:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO REMOVE, REPLACE & REFIT FRONT RADIATOR, RADIATOR FAN ASSY, AIR COND CONDENSOR, AIR COND PIPE & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL & ETC.	New	120.00 100
2	TO REMOVE, REPLACE INLET MANIFOLD, AIR CLEANER ASSY, BATTERY & ETC. BACK TO ORIGINAL OPERATIONS	New	100.00 60
3	TO REMOVE, REPLACE, REPAIR, READJUST & CHISEL FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH, FRONT WHEEL HOUSE CHASSIS LH&RH & ETC. BACK TO ORIGINAL CONDITIONS	New	850.00 800
4	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT SUPPORT PANEL, FRONT BUMPER, FRONT FENDER LH/RH & CHASSIS MEMBER LH&RH	New	1,200.00 1000
5	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00 30
6	TO REFILL AIR COND GAS & VACUUM	New	100.00
Gross Labour Cost (\$\$)			2,450.00

Mova Automotive Pte Ltd/SJV9910E/02/02/2023 15:46. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasm
Hp 90010068

7 days

h/s

03/02/23 @ 1420

EXCESS: 500

REVERT

Resurvey after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

045B

Vehicle Details

Vehicle No.:

SJV9910E

Vehicle to be Exported:

No

Intended Deregistration Date:

03 Feb 2023

Vehicle Make:

TOYOTA

Vehicle Model:

VIOS E AUTO

Primary Colour:

Silver

Manufacturing Year:

2009

Engine No.:

1NZY036071

Chassis No.:

MR053HY9305149960

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$12,717.00

Original Registration Date:

26 Feb 2010

First Registration Date:

26 Feb 2010

Transfer Count:

2

Actual ARF Paid:

\$12,717.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

25 Feb 2030

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

PQP Paid:

\$33,038.00

COE Rebate Amount:

\$23,342.00

Total Rebate Amount:

\$23,342.00

The information contained herein is correct as at 03 Feb 2023

OK