



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : ALLIANZ INSURANCE SINGAPORE PTE LTD
12 MARINA VIEW
#04-01, ASIA SQUARE TOWER 2
SINGAPORE 018961
Registration No : SDE8885L
Chassis No : MRHFC5650LT000708
Model : CIVIC 1.6 VTI YM2020
Owner's Name : LIN FEI, EPHRAIM
Ins Policy No. :
Date of Accident : 23/1/2023

Document No. : SQT23000216 **Page** 1
Date : 26. Jan 2023
Customer No. : WZA011
Svc Advisor : SUHELMI
Engine No : R16B25521001
Date | Time : 26. Jan 2023 10:28:26 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Click Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIN FEI, EPHRAIM OWNER INSURER: TOKIO MARINE ACC DATE: 23/01/2023 SURVEYED BY: DATE: REF NO: TP INSURER: ALLIANZ TP VEH: SJJ1000Y						
71101-TEA-T50ZA	FACE,FR.BUMPER <i>R</i>	1	579.90	<i>X</i> 25	434.92	34.79	469.71
71198-TEA-T01	SPACERL.FR.BUMPER SIDE <i>11</i>	1	10.40	<i>X</i> 25	7.80	0.62	8.42
91505-TM8-003	CLIP,BUMPER <i>11</i>	17	2.30	<i>X</i> 25	29.32	2.35	31.67
34350-TET-H01	LIGHT ASSYL.SIDE TURN <i>SKR</i>	1	67.50	25	50.62	4.05	54.67
BO-NUM-OPC	NUMBER PLATE-OPC (N) <i>nei</i>	1	45.00		45.00	3.60	48.60
Sum Item					567.66	45.41	613.07
BO-NUM-SEAL	SEAL NUMBER PLATE. <i>nei</i>	1	80.00	<i>✓</i>	80.00	6.40	86.40
Sum Ext. Service					80.00	6.40	86.40
BOSUN	SUNDRIES <i>nei</i>	1	50.00	<i>10</i>	50.00	4.00	54.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	<i>150</i>	180.00	14.40	194.40
BKFE11K	STRAIGHTEN ALIGN FR L FENDER.	1	1500.00	<i>650</i>	1500.00	120.00	1620.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1200.00	<i>1040</i>	1200.00	96.00	1296.00
Sum Labor					2930.00	234.40	3,164.40

Survey By

Date & Time

Total Amount 3,577.66 286.21 3,863.87

Printed on 26/1/2023 10:42:57 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

3 days

21/7 # 2025-62