

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0114/2023/EQ
DATE : 1-Feb-23
WIP : 60830

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TERRENCE NG TECK LENG
ADDRESS : BLK 2 SUFFOLK WALK
#26-01
SINGAPORE 307462
TELEPHONE : HP +65 98292986
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800053988-04
VEHICLE NO : **SKE 1912 E**
MODEL CODE : AUDI S5 SPORTBACK 3.0 TFS
MODEL YEAR : 15/5/2018
ENGINE NO : CWG 069579
CHASSIS NO : WAUZZZF56JA087254
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Jan-23
PLACE OF ACCIDENT : 112 KATONG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKE 1912 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00 250. ✓	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00 1000 ✓	
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,500.00 1100 ✓	
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00 +	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 ✓	✓
TOTAL LABOUR CHARGES		:	\$ 6,252.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 1912 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Deformed</i>	1	\$ 3,313.00	✓ 2650.4	
2	FRONT BUMPER FIXING PARTS <i>x 4 m</i>	1	\$ 452.00	+	
③	FRONT BUMPER SECURING STRIP <i>the new</i>	1	\$ 42.00	✓ x	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>the new</i>	1	\$ 269.00	+	
5	FRONT BUMPER AIR GUIDE - LH <i>cut</i>	1	\$ 92.00	✓ 72.96	
6	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cut</i>	1	\$ 873.00	✓ 698	
⑦	FRONT BUMPER GUIDE SECTION - LH <i>the new</i>	1	\$ 43.00	✓ x	
8	FRONT BUMPER TOP COVER	1	\$ 151.00	+	
9	CAUTION SIGN STICKER <i>the new</i>	1	\$ 17.00	+	
10	AIR CONDITIONER STICKER	1	\$ 9.00	+	
11	FRONT PARKING AID SENSOR - OUTER	1	\$ 272.00	+	
12	FRONT PARKING AID SEAL RING	4	\$ 11.00	+	
13	HORN HIGH TONE - LH	1	\$ 142.00	+	
14	HORN BRACKET - LH	1	\$ 35.00	+	
15	FRONT FENDER - LH <i>Deformed</i>	1	\$ 1,258.00	✓ 1006.4	
①⑥	FRONT FENDER CLOSING ELEMENT - LH <i>Deformed</i>	1	\$ 88.00	✓ 70 ✓	
①⑦	FRONT FENDER BRACKET - LH <i>the new</i>	1	\$ 44.00	✓ 34.8 ✓	
18	FRONT FENDER RIVET <i>the new</i>	6	\$ 24.00	✓ 19.2	
①⑨	FRONT FENDER BRACE - LH <i>the new</i>	1	\$ 140.00	+	
20	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH <i>the new</i>	1	\$ 59.00	+	
SUB TOTAL SPARE PARTS			\$ 7,334.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 1912 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
(21)	FRONT FENDER BRACKET - LH CENTER <i>new</i>	1	\$ 42.00	? X
22	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 322.00	+
(23)	FRONT WHEEL SPOILER <i>new to n</i>	1	\$ 87.00	+ 68.96 ✓
24	FRONT WHEEL SPOILER END PLATE - LH <i>new</i>	1	\$ 42.00	+
25	FRONT WHEEL SPOILER STONE CHIP GUARD - LH <i>new</i>	1	\$ 60.00	+
26	FRONT WHEEL SPOILER TRIM BRACKET - LH <i>new</i>	1	\$ 29.00	+
27	FRONT FENDER CHROME TRIM - LH <i>new</i>	1	\$ 217.00	✓ 173.6
(28)	FRONT FENDER LEDGE COVER - LONG <i>new</i>	1	\$ 42.00	? X
(29)	FRONT FENDER LEDGE COVER - LH SHORT <i>new</i>	1	\$ 19.00	✓ 14.8 ✓
30	HEADLIGHT - LH <i>new</i>	1	\$ 8,909.00	✓ 7127.2
31	LIFT CYLINDER - LH <i>new</i>	1	\$ 230.00	+
32	LIFT CYLINDER BRACKET - LH <i>new</i>	1	\$ 17.00	+
33	LIFT CYLINDER CORRUGATED PIPE	1	\$ 104.00	+
34	RADIATOR AIR GUIDE - LH INNER	1	\$ 38.00	+
35	RADIATOR AIR GUIDE - LH OUTER	1	\$ 25.00	+
36	RADIATOR AIR GUIDE - UPPER	1	\$ 25.00	+
37	RADIATOR AIR GUIDE - LH	1	\$ 53.00	+
38	FRONT ALUMINIUM RIM - LH <i>new</i>	1	\$ 2,502.00	+
39	FRONT ALUMINIUM RIM RUBBER VALVE <i>new</i>	1	\$ 4.00	+
(40)	SUNDRIES <i>Not New</i>		\$ 400.00	? X
TOTAL SPARE PARTS		:	\$ 20,501.00	
TOTAL LABOUR CHARGES		:	\$ 6,252.00	
GRAND TOTAL		:	\$ 26,753.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Admin Lj
SURVEYED DATE : 02/02/23.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT