Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Attn:

Singapore 079120

Chew, Yvonne

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Date: 03 Feb 2023

Preliminary Advice

Vehicle No : SKE1912E Accident Date : 28/01/2023 : AUDI S5 SPORTBACK Policy No. : 1800053988-04 Make

Assignment Date : 03/02/2023 Excess : S\$0.00 Date of Inspection : 02/02/2023 Est. Duration of Repair : 4

Inspection At

55 UBI ROAD 1 SINGAPORE 408699

: PREMIUM AUTOMOBILES PTE LTD (UBI)

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,753.00
Revised Amount	:S\$	17,684.00
Check Items (Estimated)	:S\$	772.00
Total	:S\$	18,456.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 230,000.00 COE / PARF Rebate :S\$ 83,644.00

Salvage Value :S\$

Margin for Repair :S\$ 146,356.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir	ndly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.