

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0119/2023/EQ
DATE : 2-Feb-23
WIP : 61292

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAU CHONG WAI
ADDRESS : BLK 324 CLEMENTI AVENUE 5
#03-219
SINGAPORE 120324
TELEPHONE : HP +65 97822208
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100487284-06
VEHICLE NO : **SCW 368 H**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 24/10/2016
ENGINE NO : CZC 562537
CHASSIS NO : WAUZZZ8V7G1103483
MILEAGE : 67,132
DATE IN : 1-Feb-23
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Jan-23
PLACE OF ACCIDENT : ISLAND CLUB ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCW 368 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	360.00 ?
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	350.00 250
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. RENEW WHERE NECESSARY.	S/N \$ 1,400.00	? 1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,000.00	5,000.00 1500
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS ^{LHS} FRONT FENDER TOP SUPPORT AND BONNET.	\$ 3,700.00	3,700.00 2200
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	192.00
TOTAL LABOUR CHARGES		: \$ 11,002.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCW 368 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>turn /</i>	1	\$	2,515.00	
2	FRONT BUMPER FIXING PARTS <i>m /</i>	1	\$	207.00	
3	FRONT BUMPER TRIM COVER - RH <i>mis /</i>	1	\$	193.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$	185.00	
5	FRONT BUMPER PULL STRAP - LOWER <i>cm /</i>	4	\$	245.00	
6	FRONT BUMPER GUIDE SECTION - RH <i>cm /</i>	1	\$	46.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>mis /</i>	1	\$	129.00	
8	RADIATOR GRILLE <i>cm /</i>	1	\$	813.00	
9	RADIATOR GRILLE COVER <i>?</i>	1	\$	116.00	
10	CAUTION SIGN STICKER <i>m /</i>	1	\$	17.00	
11	AIR CONDITIONER STICKER <i>m /</i>	1	\$	9.00	
12	FRONT BUMPER REINFORCEMENT BEAM <i>st /</i>	1	\$	896.00	
13	FRONT BUMPER FOAM FILLER PIECE <i>cm /</i>	1	\$	163.00	
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>?</i>	1	\$	67.00	
15	HORN HIGH TONE - RH <i>st /</i>	1	\$	225.00	
16	FRONT FENDER - RH <i>st /</i>	1	\$	1,012.00	
17	FRONT FENDER ATTACHMENT PARTS <i>?</i>	1	\$	80.00	
18	FRONT FENDER BRACKET - CENTER <i>st /</i>	1	\$	57.00	
19	FRONT FENDER RIVET <i>m /</i>	6	\$	24.00	
20	FRONT FENDER BRACE <i>?</i>	1	\$	114.00	
SUB TOTAL SPARE PARTS		:	\$	7,113.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCW 368 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER BRACKET - REAR ?	1	\$	38.00	
22	FRONT WHEEL HOUSING LINER - RH CA✓	1	\$	198.00	
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	1	\$	99.00	
24	BONNET SA✓	1	\$	3,412.00	
25	BONNET HINGE - LH / RH SA✓	2	\$	146.00	
26	BONNET EDGE PROTECTION ne✓	1	\$	33.00	
27	BONNET STRIKER ?	1	\$	130.00	
28	BONNET LOCK WITH MICRO-SWITCH X	1	\$	241.00	
29	BONNET CATCH HOOK ?	1	\$	106.00	
30	BONNET CATCH HOOK ?	1	\$	75.00	
31	BONNET LOCK CABLE X	1	\$	87.00	
32	BONNET SIDE SEAL - LH / RH X	2	\$	102.00	
33	BONNET BOWDEN CABLE X	1	\$	67.00	
34	BONNET ENGINE SOUND ABSORBER X	1	\$	260.00	
35	FRONT PLENUM CHAMBER COVER ?	1	\$	211.00	
36	HEADLIGHT GAS DISCHARGE LAMP - RH CA✓	1	\$	2,975.00	
37	HEADLIGHT POWER MODULE ?	1	\$	690.00	
38	GAS DISCHARGE LAMP ?	1	\$	462.00	
39	GAS DISCHARGE LAMP CONTROL UNIT ?	1	\$	1,390.00	
40	HEADLIGHT HOSE ?	1	\$	62.00	
SUB TOTAL SPARE PARTS		:	\$	10,784.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCW 368 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	LIFT CYLINDER - RH <i>cm</i>	1	\$	223.00
42	LIFT CYLINDER HOSE <i>?</i>	1	\$	208.00
43	LOCK CARRIER <i>?</i>	1	\$	854.00
44	A/C CONDENSER <i>?</i>	1	\$	586.00
45	A/C CONDENSER REFRIGERANT LINE <i>?</i>	1	\$	627.00
46	A/C CONDENSER REFRIGERANT LINE <i>?</i>	1	\$	503.00
47	A/C CONDENSER REFRIGERANT LINE <i>?</i>	1	\$	539.00
48	ADDITIONAL RADIATOR <i>?</i>	1	\$	967.00
49	RADIATOR BRACKET - LH / RH <i>?</i>	2	\$	92.00
50	RADIATOR BUSH - LH / RH LOWER <i>?</i>	2	\$	22.00
51	READY-MIX COOLANT <i>?</i>	6	\$	326.00
52	RADIATOR <i>?</i>	1	\$	1,099.00
53	RADIATOR AIR GUIDE - RH <i>?</i>	1	\$	36.00
54	RADIATOR AIR GUIDE SEAL - RH OUTER <i>?</i>	1	\$	10.00
55	RADIATOR AIR GUIDE - UPPER CENTRE <i>?</i>	1	\$	20.00
56	FRONT AIR DUCT UPPER COVER <i>?</i>	1	\$	31.00
57	RADIATOR AIR DUCT <i>?</i>	1	\$	60.00
58	RADIATOR AIR DUCT <i>?</i>	1	\$	21.00
59	OUTSIDE TEMPERATURE SENSOR BRACKET <i>ne</i>	1	\$	22.00
60	FRONT NO PLATE <i>Y</i>	S/N	\$	60.00
61	SUNDRIES <i>?</i>		\$	500.00
TOTAL SPARE PARTS		:	\$	24,703.00
TOTAL LABOUR CHARGES		:	\$	11,002.00
GRAND TOTAL		:	\$	35,705.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasul - Hp 90010368
: 02/02/23 @ 1400
: 6 days
: Repair
: EXCESS: TBA
: Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT