

ASS. REC. BY:

REP:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNH 84852 Yr Regn: 2022 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q5 c.c. 1984

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 2816 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZFV6N2114950

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/60R18

R: 235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 14/02/23

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP SMRT.

MV:

PV:

Nett:

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

_____ S + RS. _____ SI

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

Report Format: _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0143/2023/EQ
DATE : 7-Feb-23
WIP : 61387

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SMB 5016 H**

STRIDES AUTOMOTIVE SERVICES Pte Ltd

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

Attn: Motor Claims Dept

OWNER'S NAME : AUDI SINGAPORE PTE LTD
ADDRESS : 8 KALLANG AVENUE
#08-01 APERIA TOWER 1
SINGAPORE 339509
TELEPHONE : HP +65 92333513
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SD22V02091/VPC/R02
VEHICLE NO : **SNH 8485 Z**
MODEL CODE : AUDI Q5 2.0 TFSI QU S-TRONIC
MODEL YEAR : 30/11/2022
ENGINE NO : DMS 100283
CHASSIS NO : WAUZZZFY6N2114950
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Jan-23
PLACE OF ACCIDENT : BUKIT TIMAH SLIP ROAD TOWARDS ADAM ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNH 8485 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	✓
3	TO REMOVE AND RENEW REAR WINDSCREEN.	S/N \$	480.00	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN .	S/N \$	400.00	✓
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	✓
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	1600
TOTAL LABOUR CHARGES		:	\$ 4,320.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNH 8485 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	✓ TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS. ✓	\$ 4,000.00	2800 ✓
8	✓ TO CARRY OUT DIAGNOSTIC CHECK. ✓	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,512.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNH 8485 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER - UPPER / LOWER <i>Repair Deleted Repair</i>	1	\$ 3,600.00 <i>+</i>	<i>Pricing ??</i>	
2	REAR BUMPER LOWER TRIM - LH / RH <i>new</i>	2	\$ 272.00 <i>+</i>		
3	REAR BUMPER SPOILER <i>Deleted</i>	1	\$ 382.00 <i>✓</i>		
4	REAR BUMPER TOW EYE COVER - LH / RH <i>new</i>	2	\$ 113.00 <i>+</i>		
5	REAR BUMPER DIFFUSER <i>Deleted new</i>	1	\$ 398.00 <i>+</i>		
6	REAR BUMPER CORNER TRIM - LH / RH <i>new</i>	2	\$ 580.00 <i>+</i>		
7	REAR BUMPER TRIM - CENTER <i>deleted</i>	1	\$ 198.00 <i>✓</i>		
8	REAR BUMPER TAIL LIGHT - LH / RH <i>?</i>	2	\$ 1,652.00 <i>?</i>		
9	REAR LID TAIL LIGHT - LH / RH <i>new</i>	2	\$ 2,942.00 <i>+</i>		
10	REAR LICENCE PLATE LIGHT - LH / RH <i>new</i>	2	\$ 119.00 <i>+</i>		
11	REAR BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 1,104.00 <i>+</i>		
12	REAR BUMPER IMPACT BAR GASKET - LH / RH <i>new</i>	2	\$ 7.00 <i>+</i>		
13	REAR BUMPER HOLDING STRAP <i>new</i>	1	\$ 201.00 <i>+</i>		
14	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 200.00 <i>+</i>		
15	REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 543.00 <i>+</i>		
16	REAR PARKING AID SEAL RING <i>new</i>	4	\$ 11.00 <i>+</i>		
17	REAR LID <i>Deleted</i>	1	\$ 5,267.00 <i>✓</i>		
18	REAR LID ATTACHMENT PARTS <i>new</i>	1	\$ 179.00 <i>+</i>		
19	REAR LID FLAP GASKET <i>new</i>	1	\$ 456.00 <i>+</i>		
20	REAR LID LOCK WITH MICROSWITCH <i>new</i>	1	\$ 267.00 <i>+</i>		
SUB TOTAL SPARE PARTS		:	\$ 18,491.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNH 8485 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET LOCK COVER <i>New</i>	<i>New</i> 1	\$ 9.00	+
22	REAR LID LOCK ACTUATOR WITH CAMERA PUSHBUTTON	1	\$ 1,550.00	+
23	PACKING ADHESIVE	1	\$ 22.00	✓
24	AUDI EMBLEM	1	\$ 152.00	✓
25	"Q5" INSCRIPTION	1	\$ 110.00	✓
26	"QUATTRO" INSCRIPTION	1	\$ 110.00	✓
27	REAR WINDOW <i>New</i>	1	\$ 1,348.00	✓
28	WINDOW PRIMER <i>New</i>	1	\$ 24.00	✓
29	REAR SPOILER - LH / RH <i>New</i>	2	\$ 550.00	✓
30	REAR TAILGATE TRIM STRIP <i>New</i>	1	\$ 349.00	+
31	REAR WHEEL COVER - LH / RH <i>New</i>	2	\$ 1,306.00	✓
32	REAR NUMBER PLATE <i>2. New</i>	S/N	\$ 60.00	+
33	REAR WINDSCREEN SEALANT <i>New</i>	S/N	\$ 200.00	✓
34	SUNDRIES		\$ 500.00	✓
TOTAL SPARE PARTS		:	\$ 24,781.00	
TOTAL LABOUR CHARGES		:	\$ 8,512.00	
GRAND TOTAL		:	\$ 33,293.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *14/02/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 05 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT