51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: HSBC LIFE (SINGAPORE) PTE LTD DATE: 14/2/2023

Survey details

| Date of loss | 27/1/2023 |
|---------------------|----------------|
| Date of appointment | 3/2/2023 |
| Date of survey | 6/2/2023 |
| Location of survey | PRIMERO RACING |
| | |

Vehicle Details:

| Claim Type: | THIRD PARTY |
|----------------------|--------------|
| Vehicle number | FBQ 3109M |
| Make and Model | BMW S1000R R |
| Date of registration | 29/7/2013 |
| Excess | |
| Market Value | \$12,000.00 |
| Parf Rebate | \$78.00 |
| Nett Loss | \$11,922.00 |

Repair details

| | Initial Estimate |
|--|------------------|
|--|------------------|

Proposed/Revised repair cost:

| Parts | |
|--------------------------|--|
| "Check items (Estimated) | |
| Labour | |
| Total | |
| Lump Sum (Estimated) | |
| | |

Number of days of repair 4 days (est)

Remarks:

Damages Consistent

The estimated repair cost of the damaged vehicle is in the region of \$4,000.00-\$5,000.00