

<< Service Request Details

Claim	S3M04II9
Reference	CS3/HSB23001146/Rvp3e2 
Loss Date	27 January 2023
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	30 Jan 2023 9:39:43 AM
Request Date	3 February 2023
Due Date	

Actions

Next Step Add invoice

Add Invoice

Vehicle Information

Incident FBQ3109M
Vehicle
Registration #

Make TPVD BMW

Model S 1000RR

Service Address

, , ,

Primary Contact/Insured

Services

Pre-Repair Survey

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

LOW Garnet

garnet.low@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Invoice



Surveyor/ Assessor expense



Upload Documents

Already Attached

NAME

DATE UPLOADED

NAME

TYPE

SUBTYPE

AUTHOR

DATE UPLOADED

HSB-LKKInvoice-AC2300852.pdf.pdf

Invoice

Surveyor/
Assessor expenseLKK AUTO CONSULTANTS
PTE LTD (TP)15 February
2023

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	15 February 2023
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	15 February 2023
 FBQ 3109M ia prs.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 February 2023
 -.mp4	Evidence	Videos	LOW Garnet	3 February 2023
 EMAIL FRM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	3 February 2023
 FBQ3109M TP GIA REPORT.pdf.pdf	Other	Other	CHU Xichi Eugene	2 February 2023
 OI GIA REPORT - SH9645M.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	31 January 2023