

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

Email: soonosanmotor@gmail.com

To: Motor Claims Dept

MSIG INSURANCE (Singapore) PTE LTD

4,Shenton Way #21-01

SGX Centre2 S,pore 068807

Accident date:09/11/2022

Date:03/02/2023

Estimate cost to repair vel: SJN 4476S (Honda Stream) claims under vel: FBJ324P.

1pce Frog lamp <i>new</i>	\$ 298.00 X	
1pce bonnet <i>dent</i>	\$ 1,100.00	689.
1pce front griller <i>crushed</i>	426.00	268.
1pce front griller outer moulding <i>ut</i>	380.00	280
1pce front griller RSZ plate <i>new</i>	120.00	45.
6pcs front griller inner clips@\$6 <i>new</i>	36.00	30.
1pce front griller emblem <i>new</i>	98.00	48.
1pce right headlamp <i>crushed</i>	788.00	685
1pce front bumper <i>dent</i>	988.00	683.
1pce front bumper lower griller <i>dent</i>	380.00	87
10pcs front bumper inner clips@\$5 <i>new</i>	50.00	30.
10pcs Bonnet insulator clips 1/8 x 10 #80	\$ 4,366.00	
Less 20% <i>new</i> X.	873.20	
	\$ 3,492.80	
To rustproof	150.00	30
To dismantle/renew accident portion	1,000.00	500
To spray paint	1,000.00	400
Total:	\$ 5,642.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L.

1/s 06/02/23.

04 Days

total: 3206.

h/s: 2550 ✓