

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 10 May 2023

Preliminary Advice

Insured Vehicle No	: FBJ324P	Accident Date	: 09/11/2022
TP Vehicle No	: SJN4476S	Assignment Date	: 03/02/2023
Make	: HONDA STREAM	Est. Duration of Repair	: 4
Date of Inspection	: 06/02/2023		
Inspection At	: SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408700		

Point of Impact / General Description of Damages

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,945.20
Revised Amount	:S\$	3,206.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,206.00
Lump Sum Repair	:S\$	2,550.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.