

VERON

FBL2418D

Accident along tanglin Road towards Tanglin mall

S/N	Qty	Description	(S\$)	
<u>Parts</u>				
1	1pcs	Front Mudguard <i>cm</i>	\$	75.00
2	1pcs	Front Wheel <i>Xnn</i>	\$	350.00
3	1pcs	Front Wheel Shaft <i>bt</i>	\$	130.00
4	1pcs	Front Wheel Bearing <i>ne</i>	\$	80.00
5	1pcs	Front Disc Rotor <i>X Repair</i>	\$	200.00
6	2pcs	Front Fork Assy LH & RH @240 <i>bt</i>	\$	480.00
7	1pcs	Stem Steering <i>bt</i>	\$	165.00
8	1pcs	Handlebar <i>Xnn</i>	\$	80.00
9	1pcs	Clutch Lever <i>Xnn</i>	\$	40.00
10	1pcs	Brake Lever <i>Xnn</i>	\$	40.00
11	2pcs	Balancer @25/pcs <i>Xnn</i>	\$	50.00
12	2pcs	Side Mirror @30/pcs <i>scr</i>	\$	60.00
13	1pcs	Front Headlamp Cover <i>scr</i>	\$	60.00
14	2pcs	Front Signal Lamp @35/pcs <i>cm</i>	\$	70.00
15	1pcs	Headlight Assy <i>Xnn</i>	\$	160.00
16	1pcs	Front Mask <i>cm</i>	\$	90.00
17	1pcs	Front Mask Base <i>cm</i>	\$	120.00
18	1pcs	Pilot Light <i>Xnn</i>	\$	250.00
19	1pcs	Belly shield covering <i>cm</i>	\$	90.00
20	1pcs	Front Side Fairing LH <i>cm</i>	\$	95.00
21	1pcs	Front Side Fairing RH <i>cm</i>	\$	95.00
22	1pcs	Rear Side Fairing LH <i>Xnn</i>	\$	95.00
23	1pcs	Rear Side Fairing RH <i>Xnn</i>	\$	95.00
24	1pcs	Centre covering <i>cm</i>	\$	120.00
25	1pcs	Front Footrest Bar <i>Xnn</i>	\$	75.00
26	2pcs	Front Footrest Rubber @45/pcs <i>Xnn</i>	\$	90.00
27	1pcs	Gear Padal <i>Xnn</i>	\$	50.00
28	1pcs	Rear LH Foot Rest <i>Xnn</i>	\$	45.00
29	1pcs	Rear LH Foot Rest Bracket <i>Xnn</i>	\$	80.00
30	1pcs	Exhaut pipe <i>Xnn</i>	\$	400.00
31	1pcs	Box Rack <i>Xnn</i>	\$	120.00
32	1pcs	Rear Top Box <i>Xnn</i>	\$	150.00
33	1pcs	Front Basket <i>cm</i>	\$	70.00
34	1pcs	Radiator <i>bt</i>	\$	380.00
35	1pcs	Front Caliper <i>X repair</i>	\$	250.00
36	1pcs	Front Rim <i>bt</i>	\$	250.00
37	1pcs	Front Tyre <i>cut</i>	\$	120.00
38	1pcs	Pillion Footrest (LH) <i>bro</i>	\$	45.00
			Total	\$ 5,215.00
			-10%	\$ 521.50
			Parts Sub Total	\$ 4,693.50
<u>Special Nett</u>				
32	1pcs	Front fork seal <i>ne</i>	\$	80.00
33	1pcs	Front fork oil <i>ne</i>	\$	300.00

34	1pcs	IU Unit <i>Xm</i>	270	\$	160.00	<i>X</i>
35	1pcs	No. plate (front) <i>new</i>		\$	20.00	
36	1set	Body sticker <i>new</i>		\$	150 180.00	

Total \$ 740.00

Labour					
1	Towing		\$	40	100.00
2	To realign body frame		\$	300	350.00
3	To R&R fornt suspension, handle bar, headlamp, side fairing, and attachments.		\$	300	400.00
		Labour Total:	\$		850.00
		Sub Total (labour and parts):	\$		6,283.50

Vehicle is at **5 Soon Lee Street #01-02 Pioneer Piont S(627607)**

Please arrange your surveyor to come down to survey the vehicle.

Contact : **Daryl 98356259**

2155.50
270.00
640.00

3065.50

20%
2452.40

H/S - \$2,450 / 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: