

TP Budget 812/10

FONG MOTORS				
1 Kaki Bukit Ave 6 #01-27/45				
AutoBay@ Kaki Bukit, Singapore 417883				
Tel: 6748 5648, Email: fongmotors@gmail.com				
Estimate of Cost of Repairs				
				Date
				Vehicle No.
				Model
				CHASSIS/ENG#
PARTS				
S/N	Item	Quantity	Unit Price	Amount
1	REAR WINDSCREEN GLASS MOULDING <i>new</i>	1	\$108.50	\$108.50 ✓
2	REAR TAIL GATE <i>Detached</i>	1	\$1,485.00	\$1,485.00 ✓
3	EVERY - STICKER <i>3 new</i>	1	\$49.80	\$49.80 ✓
4	LOGO - EMBLEM	1	\$38.80	\$38.80 ✓
5	TAIL GATE OUTER HANDLE <i>Detached</i>	1	\$85.80	\$85.80 ✓
6	TAIL GATE INNER BOARD <i>new</i>	1	\$298.00	\$298.00 x
7	REAR WEATHERSTRIP <i>new</i>	1	\$139.80	\$139.80 ✓
8	REAR BUMPER <i>Detached</i>	1	\$796.00	\$796.00 ✓
9	REAR PANEL <i>Detached</i>	1	\$408.00	\$408.00 ✓
10	REAR TAIL GATE LOCK <i>Detached</i>	1	\$132.00	\$132.00 ✓
11	REAR BUMPER LAMP <i>new</i>	2	\$68.80	\$137.60 ✓
12	STAY PANEL LOCK SCREW CARRIAGE <i>new</i>	1	\$48.90	\$48.90 x
13	REAR EXHAUST PIPE <i>new</i>	1	\$425.80	\$425.80 x
Sub-total 1				\$4,154.00
NETT ITEMS				
S/N	Item	Quantity	Unit Price	Amount
1	REAR WINDSCREEN GLASS SEALANT <i>new</i>	1	\$60.00	\$60.00 ✓
2	REAR NUMBER PLATE <i>new</i>	1	\$35.00	\$35.00 ✓
3	BUMPER CLIP SET <i>new</i>	1	\$30.00	\$30.00 ✓
4	STICKER - 5PAX & 70KM <i>new</i>	1	\$30.00	\$30.00 ✓
5	Reverse Camera <i>new</i>	500		
6	Reverse Sensor <i>new</i>	200		
Sub-total 2				\$155.00
LABOUR				
1	TO KNOCK & CHANGE PARTS			\$800.00 <i>700</i>
2	REMOVE & REFIX REAR WINDSCREEN GLASS			\$150.00 <i>120</i>
3	SPRAY REAR AFFECTED PARTS			\$800.00 <i>600</i>
4	END PANEL SEALANT			\$80.00 <i>60</i>
5	TO REMOVE AND REFIX EXHAUST SYSTEM			\$120.00 x
6	TO CONDUCT WIRING CHECKS			\$50.00 <i>30</i>
To remove reverse sensor and rear camera				
Labour Total				\$2,000.00
Parts & Labour Total				\$6,309.00

3381.30
2874.10

355

1710

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 4939
4/5: 3.9K
05 Days
3.9K