

TAN CHONG MOTOR SALES PTY. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

Rasyi

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0032/2023
DATE : 01-FEB-2023

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MR WU XIANGYU
ADDRESS : 19 SHELFORD ROAD
#09-08
S(288408)
TELEPHONE NO : 84266879/96678337

LICK

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBA4556H
VEHICLE NO : SMS3871D
MODEL CODE : BDTARCZB17EWA----K19
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019
ENGINE NO : HR16950696C
CHASSIS NO : MNTBBAB17Z0037204
MILEAGE : 1 KM
DATE IN : 01/02/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 30/01/2023

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMS3871D

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RCI	R/INSTALL OR RENEW REVERSE CAMERA ASSIT TO REPAIR	120.00	X ✓ 120 m ✓
2 RISCO	REMOVE/INSTALL SEAT & CUSHION CARPET	240.00	240.00 120 X 120 m ✓
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR 3X AFFECTED PANEL	360.00	120 ✓
4 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/ ✓
5 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	/ ✓
6 ZZ/001	REPAIR RH/LH RR FENDER & RR FLOOR PANEL RENEW RR BUMPER, END PANEL & TRUNKLID	1560.00	1170 1365 ✓
7 ZZ/002	S/PAINT RH/LH RR FENDER, RR END PANEL, RR BUMPER, TRUNKLID, RR FLOOR PANEL	1600.00	750 1250 ✓
8 ZZ/003	TRANSFER MECHANISM PART FOR TRUNKLID	60.00	/ ✓
9 ZZ/004	CHECK RR LIGHTING	48.00	/ ✓
TOTAL LABOUR CHARGES		4243.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMS3871D

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 HINGE TRUNK(\$44.2X2) <i>X n</i>	H4400-3RAMA	88.40	<i>X</i>		
2 FINISHER ASSY <i>ca</i>	84810-3ST1A	199.40	<i>✓</i>		
3 COMB LAMP RR <i>? X n</i>	26555-3SN5E	250.00	<i>X</i>		
4 COMB LAMP <i>? X n</i>	26550-3SN3E	250.00	<i>X</i>		
5 ABSORBER ENERGY <i>? X n</i>	85090-3SN5A	205.00	<i>X</i>		
6 COMB LAMP <i>? X n</i>	26555-3SN0D	375.00	<i>X</i>		
7 COMB LAMP <i>? X n</i>	26550-3SN0D	375.00	<i>X</i>		
8 ORNAMENT ASSY R <i>X n</i>	26560-5C000	66.90	<i>X</i>		
9 ORNAMENT ASSY L <i>X n</i>	26565-5C000	66.90	<i>X</i>		
10 R/LAMP CLIP(\$5.3X4) <i>n</i>	26557-2U000	21.20	<i>✓</i>		
11 CLIP(\$1.4X10) <i>n</i>	01553-10501	14.00	<i>✓</i>		
12 CLIP(\$1.5X10) <i>n</i>	01553-09321	15.00	<i>✓</i>		
13 CROMMET(\$2.9X2) <i>n</i>	63846-5V000	5.80	<i>✓</i>		
14 LOCK ASSY-TRUNK <i>? X n</i>	84630-3AW0A	76.50	<i>X</i>		
15 W/STRIP T/LID <i>X n</i>	84830-3SB3J	94.90	<i>X</i>		
16 EMBLEM <i>n</i>	84890-3RA0B	54.50	<i>✓</i>		
17 EMBLEM <i>n</i>	84890-3RA1B	102.90	<i>✓</i>		
18 CARPET-LUGGAGE <i>? X n</i>	84902-3SB0A	493.90	<i>X</i>		
19 PLATE-LUGGAGE <i>? X n</i>	84921-3SB0A	106.00	<i>X</i>		
20 SPACER <i>? X n</i>	84978-3SB0A	184.10	<i>X</i>		
21 PASCIA BUMPER <i>de</i>	85022-3SN5H	773.00	<i>✓</i>		
22 TRUNK LID <i>bt</i>	H430M-3SBMA	722.80	<i>✓</i>		
23 PANEL-REAR UPPE <i>repa bt</i>	G9110-3GB0A	475.90	<i>✓</i>		
24 BRET RE BUMPER <i>? X n</i>	85227-3SN5A	18.00	<i>X</i>		
25 BRET BUMPER <i>? X n</i>	85226-3SN5A	18.00	<i>X</i>		

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMS3871D

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26 STAY RR BMPR ? Xnn	85213-EE530	49.10	X	
27 STAY RR BMPR ? Xnn	85212-EE530	52.10	X	
28 REAR LICENCE PLATE ? Xnn	RLP			60.00 X
29 SUNDRIES m	NPN			30.00 20 ✓
30 REVERSE SENSOR ? Xnn	SENSOR-XP380N			144.85 X
SUB TOTAL		5154.30	0.00	234.85
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1030.86	0.00	0.00
GRAND TOTAL		4123.44	0.00	234.85
OVERALL TOTAL		4358.29		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMS3871D

TOTAL LABOUR CHARGES	4243.00
TOTAL SPARE PARTS CHARGES	4358.29
GRAND TOTAL	8601.29 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

Ryne - H 9000068

09/02/27 @ 1120

5 days

0.00

0.00

Regy before mil

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: