



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref: CS3/CTI23001156/Sqp3	
3 ANSON ROAD #16-00			Date: 03/02/2023	
SPRINGLEAF TOWERSINGAPORE 079909			Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBD 8535B		Veh. Inspected	GBC 5687X
Policy No.			Coverage (\$)	0.00
Claim No.	SNM23D200844/C02		Excess (\$)	0.00
Assign From	TAN KAH LEONG		Assign Date	02/02/2023
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date	31/01/2023		Inspection Date	03/02/2023
Survey held at	PROMPT AUTO SOLUTIONS PTE LTD			
	8 KAKI BUKIT AVENUE 4			
	#02-37 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				