

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 200002029N
CONSTANT WIND PTE LTD
NO 11 CHANGI COAST WALK

SINGAPORE 499740
TEL : FAX :
PH : 96796867 KAH SOON
ATTN :

ESTIMATE BILL

Number : EB00006189
Date : 30/01/2023
Case No : AD00013559
Vehicle No : GBE2104X
Chassis: JTFHT02P000178955
Year of Mfr 2015
Policy No
Model : TOYOTA HIACE

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	WING MIRROR RH ASSEMBLY	1.0	1,492.90	25	1,119.68
List Price - Parts Sub Total					1,119.68
2	FRONT DOOR RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					0.00
Parts Total					1,119.68
3	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	400.00	0	400.00
4	SPRAY PAINT ON THE AFFECTED AREAS	1.0	400.00	0	400.00
5	ANTI-RUST COATING	1.0	50.00	0	50.00
Labour 1 Sub Total					850.00
SINGAPORE DOLLARS : TWO THOUSAND ONE HUNDRED TWENTY-SEVEN AND CENTS TWENTY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		1,969.68
			GST 8.00%		157.57
			TOTAL		2,127.25

Date of accident : 24/01/2023 12:20 PM. Place : ADMIRALTY ROAD WEST

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE