

Your Ref : D22003755MFCV

Date: 10<sup>th</sup> Feb 2023

Our Ref : CS/FCI23001158/Dwy3e2

**M/s MS First Capital Insurance Ltd**

16 Raffles Quay

#42-01 Hong Leong Building

Singapore 048581

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO. FBG 7783S  
INSURED VEHICLE NO. GBB 1685H  
ACCIDENT ON 24/11/2022**

Instruction was received to inspect the vehicle Reg. No. FBG 7783S. The inspection was conducted on 03/02/2023 at the premises of M/s SG 98 Motor Pte Ltd, Blk 4001 Ang Mo Kio Industrial Park 1 #01-21, Singapore 569622.

The following vehicle information was recorded:

Registration Number	: FBG 7783S
Make/Model	: Honda PCX125
Year of Registration	: 2012
Body Colour	: Black
Chassis Number	: MLHJF28A3A5048203
Engine Capacity	: 125 cc

The vehicle sustained damages at the front and o/s front. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 9,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 5,269.00)
Nett Liability	<u>S\$ 3,731.00</u> =====

Vehicle Inspected By:



ANG BRYAN TANI  
Automotive Assessor / Investigator



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MII(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.