



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23001159/Uqy3q2	
			Date: 02/03/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNB 1557C	Veh. Inspected	SLE 1532G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2300457/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	03/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESTIMA (A)	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	ACR507079482	Colour	WHITE
	Odometer	175497 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50Z R18	MARSHAL	6 mm
	L/H Front Tyre	235/50Z R18	MARSHAL	6 mm
	R/H Rear Tyre	235/50Z R18	MARSHAL	6 mm
	L/H Rear Tyre	235/50Z R18	MARSHAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR & REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/01/2023	Inspection Date	08/02/2023
	Survey held at	KAIZEN MOTORS (ENGINEERING) PTE LTD 68 KAKI BUKIT AVENUE 6 #02-12 ARK@KB SINGAPORE 417896		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	