

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	R	ef:	CS3/CTI22002976/Dnp3e2-1	
	C/O KELVIN CHIA 1 HARBOURFRON KEPPEL BAY TOW		D	ate:	21/03/2023	
			С	ode:	СТІ	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PC 7914L	Veh. Inspected		SMG 3212U	
	Policy No.	DMB1SNW00017002100	Coverage (\$)		0.00	
	Claim No.	SS/AR/2022003233/CI/PI+PD	Excess (\$)		0.00	
	Assign From	HAZDI (KC PARTNERSHIP)	Assign Date		02/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	GP72000716	Colour		GREY	
	Odometer	330553 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	GOODYEAR		5 mm	
	L/H Front Tyre	185/60 R15	GOODYEAR		5 mm	
	R/H Rear Tyre	185/60 R15	GOODYEAR		5 mm	
	L/H Rear Tyre	185/60 R15	GOODYEAR		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/03/2022	Inspection Date		31/03/2022	
	Survey held at	V-TECH AUTO SERVICE				
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				