

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/CTI23001162/Rnp3						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS3/CTI22002970/Ety 3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	3 4/93/292 2 02/02/2023	
				Code:	СТІ	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	PC 7914L	Veh. Inspected	k	SMG 3212U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM22D202180/C02/PC7914L/ TAYHP	Excess (\$)		0.00	
	Assign From HAZ	IRENE TAY ZDI (KC PARTNERSHIP)	Assign Date		3 4/93/202 2 02/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	29/03/2022	Inspection Dat	te	31/03/2022	
	Survey held at	eld at V-TECH AUTO SERVICE				
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					