



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22009013/Rny3m4-1	Date: 23/02/2023
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 2863C	Veh. Inspected	SKA 9372G	
Policy No.		Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/026285	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	03/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180K	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDD2040452A519810	Colour	BLUE	
Odometer	161046 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	HANKOOK	6 mm	
L/H Front Tyre	225/45 R17	HANKOOK	6 mm	
R/H Rear Tyre	225/45 R17	HANKOOK	6 mm	
L/H Rear Tyre	225/45 R17	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/09/2022	Inspection Date	14/09/2022	
Survey held at	HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	