



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H



REPAIR PERFORMA INVOICE

Vehicle number SLH8293J
Make / Model TOYOTA ALTIS
Chassis number MR053REH104562044
Accident date 26/1/23
Reference 2301-28

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER	620 648.45 <i>de</i>
2	REAR BUMPER RETAINER	264.66 <i>X</i>
2	REAR BUMPER REFLECTOR	153.56 <i>X</i>
1	REAR BUMPER BRACKET	240.46 <i>X</i>
1	REAR BUMPER REINFORCEMENT	398.70 439.45 <i>bt</i>
1	BOOTLID	922.79 <i>X</i>
1	BOOTLID EMBLEM - LOGO	69.81 <i>X</i>
1	BOOTLID EMBLEM - COROLLA	58.65 <i>X</i>
1	BOOTLID EMBLEM - ALTIS	61.16 <i>X</i>
1	BOOTLID WEATHERSTRIP	193.38 <i>X</i>
1	BOOTLID LOCK	439.45 <i>X</i>
1	BOOTLID LOCK STRIKER	45.30 <i>X</i>
1	BOOTLID INNER TRIM	400.73 <i>X</i>
1	END PANEL	781.44 <i>R</i>
1	END PANEL TOP GARNISH	266.09 <i>X</i>
		4985.38
	Less 25 %	1514.80
	Subtotal	4544.40
	Balance C/F	4544.40
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	REAR BUMPER CLIP	30.00 <i>neu</i>
1 SET	REAR REVERSE SENSOR	250.00 <i>200</i>
1 SET	BOOTLID INNER TRIM	30.00 <i>X</i>
	Subtotal	310.00
	Balance C/F	4854.40
LABOUR AND MISCELLANEOUS CHARGES		
1	CHECK WIRING AND LIGHTING SYSTEM	100.00 <i>X</i>
2	REMOVE & REFIT TRIMS AND GARNISHES FOR REPAIR	200.00 <i>60</i>
3	REMOVE & REPLACE REVERSE SENSOR	150.00 <i>30</i>
4	REMOVE & REPLACE EXHAUST SILENCER	150.00 <i>X</i>
5	REMOVE & REFIT BOOTLID TRIMS & ATTACHMENT	150.00 <i>X</i>
6	PANEL BEATING ON AFFECTED AREAS	1000.00 <i>300</i>
7	SPRAY PAINTING ON AFFECTED AREAS	1000.00 <i>300</i>
8	APPLY ANTI RUST ON AFFECTED AREAS	100.00 <i>X</i>
	Subtotal	2850.00
	Grand total	7704.40

1018.70
764.02

230

690

764.02
230
690

1684.02
1513.50
02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
wp 13/2/23 2140pm
L/S Resurvey after repair
tanpin e lkhant-wm
02 days