

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2301-074
DATE : 1-Feb-2023
POLICY NO. : BD P10604048R01
VEHICLE REG. NO. : SMD38568
VEHICLE MAKE : MERCEDES BENZ B180 STYLE

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper	1	\$ 1,800.00	\$ 1,800.00
2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
3	Headlamp LH	1	\$ 3,400.00	\$ 3,400.00
4	Front Radiator Grille Base	1	\$ 150.00	\$ 150.00
5	Front Radiator Grille Chrome	1	\$ 680.00	\$ 680.00
Total Spare Parts				\$ 6,080.00
SPECIAL NETT				
				\$ -
				\$ -
Total Special Nett				\$ -
LABOUR				
6	Spray painting Front Bumper Including Blending	1	\$ 300.00	\$ 300.00
7	Replace, Repair and Refit Accident Affected Areas	1	\$ 300.00	\$ 300.00
8	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
9	OBD Diagnosis and Rectify Fault Codes	1	\$ 150.00	\$ 150.00
10	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 880.00
Amount Before Excess				\$ 6,960.00
Add GST @ 7%				487.20
Total Amount Payable				\$ 7,447.20

Estimate prepared by: Oscar Pong
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

✓
✓
X
X
X
22d
20d
X
7
15L

Not Authorized
L1 by B
Murray After Paint
2 days

Kenneth
98910663

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____