Date: 4/5/2023



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL:\\ (065)\,62563561\,FAX:\\ (065)\,62564315$

Immediate Advice

To: HSBC LIFE (SINGAPORE) PTE. LTD.

Survey Details:

Date of loss	31-Jan-2023
Date of appointment	1-Feb-2023
Date of survey	21-Feb-2023
Location of survey	AUTOMOTIVE REPAIR CENTRE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SMD3865B
Make and Model	MERCEDES BENZ B180 STYLE (1595 CC)
Date of registration	17-Aug-18
Market Value	\$ 99,000.00
Parf Rebate	\$ 40,156.00
Nett Loss	\$ 58,844.00

Repair details:

Initial Estimate	\$ 6,960.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,269.35
Check items (estimate)	\$ -
Labour	\$ 435.00
Total	\$ 1,704.35
Lump Sum(if applicable)	\$ 1,350.00

Number of days for repair	2.00 Es
---------------------------	----------------



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$

Remarks:

LIABILITY 100% - BNIL. OID REVERSE AND HIT TP.		

Mandate:

Liability(TP)	100%		100%	
Proposed repair cost (WITH GST)	\$	1,458.00	\$	1,458.00
Loss of use (3DAYS x \$80.00)	\$	240.00		NIL
Loss of rental (3DAYS x\$100.00)(W/GST)		NIL	\$	324.00
Loss of income		NIL		NIL
LTA search fees	\$	26.75	\$	26.75
Others		NIL		NIL
Proposed Total	\$	1,724.75	\$	1,808.75