

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Acknowledged by Repairer

Signature:

Date:

TO : CHINA TAIPING
ATTENTION : MOTOR CLAIMS DEPT
ESTIMATE REPORT :

DATE : 3-Jan-23

JOB TYPE : TP CLAIM

VEHICLE DETAILS

VEHICLE NO : SMP4266K
MODEL : HONDA FREED 1.5G A
CHASSIS NO

6B71098516

Xin Zoy

ACCIDENT DETAILS DATE : 3-Feb-23
TIME : 08:30HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Deletd</i>	1	\$ 1,460.30	\$ 1,460.30
2	TAIL GATE LOGO <i>her</i>	1	\$ 72.30	\$ 72.30
3	TAIL GATE EMBLEM 'FREED' <i>3pc</i>	1	\$ 76.40	\$ 76.40
4	TAIL GATE EMBLEM 'HYBRID'	1	\$ 76.40	\$ 76.40
5	TAIL GATE INNER TRIM <i>crushed</i>	1	\$ 460.00	\$ 460.00
6	TAIL GATE TOP LOCK <i>2pc</i>	1	\$ 255.90	\$ 255.90
7	TAIL GATE WEATHERSTRIP <i>2pc</i>	1	\$ 241.70	\$ 241.70
8	TAIL GATE WINDSCREEN MOULDING <i>her</i>	1	\$ 194.20	\$ 194.20
9	REAR BUMPER <i>Deletd</i>	1	\$ 1,155.60	\$ 1,155.60
10	REAR BUMPER SIDE RETAINER <i>her</i>	2	\$ 69.70	\$ 139.40
11	REAR BUMPER INNER HOLDER LH <i>7012</i>	1	\$ 80.50	\$ 80.50
12	REAR FENDER INNER TRIM LH <i>crushed</i>	1	\$ 655.50	\$ 655.50
13	REAR END PANEL (OUTER) <i>Deletd</i>	1	\$ 655.50	\$ 655.50
14	REAR END PANEL TOP GARNISH <i>Deletd</i>	1	\$ 190.00	\$ 190.00

TOTAL PRICE \$ 5,713.70

LESS 20% \$ 1,142.74

SUB TOTAL PRICE \$ 4,570.96

SPECIAL NETT ITEMS

5183.50

4146.80

1240

485

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>the m</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE INNER TRIM CLIP(SET) <i>nu</i>	1	\$ 20.00	\$ 20.00
3	TAIL GATE WINDSCREEN SEALANT <i>nu</i>	1	\$ 80.00	\$ 80.00
4	REAR BUMPER CLIP(SET) <i>nu</i>	1	\$ 20.00	\$ 20.00
5	REAR END PANEL INSULATOR SEAL(OUTER) <i>nu</i>	1	\$ 120.00	\$ 120.00
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>nu</i>	1	\$ 20.00	\$ 20.00
7	REAR REVERSE SENSOR <i>2000</i>	1	\$ 220.00	\$ 220.00

880

TOTAL \$ 530.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN	\$ 1,400.00	<i>800</i>	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,400.00	<i>800</i>	
3	TO APPLY RUST PROOFING/ UNDER COAT	\$ 250.00	<i>60</i>	
4	WIRNING, BULB CHECKING	\$ 80.00	<i>30</i>	
5	REMOVE AND REFIX UPHOLSTERY, CUSHION, SEAT TO FACILITATE REPAIR	\$ 250.00	<i>60</i>	
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>	
7	TO TRANSFER TAIL GATE MECHANISM	\$ 80.00	<i>✓</i>	
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>x</i>	
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>	
10	REMOVE AND REFIX REAR REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>	

2050

TOTAL \$3,840.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,100.96
TOTAL LABOUR COST : \$ 3,840.00
TOTAL REPAIR COST : \$ 8,940.96

APPROVED DETAILS

SURVEYOR :
CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

Adrian Lj
L/S 06/02/23.
06 days

total: 6576.80
L/S: 5.2K