

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 31-Jan-23

INSURANCE: III

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD 3633 M

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
MIRROR ASSY, OUTER REAR VIEW, LH HH	1	\$1,728.70	\$1,728.70	X
Rocker Panel Outer Garnish <i>minor broken</i>	1	\$576.00	\$576.00	✓
FRONT BUMPER COVER <i>distorted / minor broken</i>	1	\$591.75	\$591.75	✓
LAMP ASSY, FOG, LH <i>OK</i>	1	\$920.00	\$920.00	✓
FRONT BUMPER SIDE RETAINER <i>broken</i>	1	\$77.00	\$77.00	✓
UNIT ASSY, HEADLAMP, LH (LED) <i>minor broken</i>	1	\$3,455.00	\$3,455.00	✓
HEAD LAMP PANEL (LH) <i>key</i>	1	\$240.10	\$240.10	X
TOP PANEL CENTRE HH	1	\$364.98	\$364.98	X
TOP PANEL SIDE <i>key</i>	1	\$145.90	\$145.90	X
FENDER SUB-ASSY, FRONT LH <i>Distorted</i>	1	\$1,111.93	\$1,111.93	✓
FRONT FENDER SHIELD <i>ton</i>	1	\$255.00	\$255.00	✓
FRONT FENDER SHIELD CLIP <i>key</i>	1	\$14.90	\$14.90	✓
FRONT FENDER HYBRID EMBLEM, LH <i>key</i>	1	\$86.50	\$86.50	✓
BRACKET, FRONT SIDE PANEL, LH HH	1	\$86.30	\$86.30	X
EXTENSION, FRONT FENDER, LH HH	1	\$47.20	\$47.20	X
PROTECTOR, FRONT FENDER UPPER, LH HH	1	\$46.10	\$46.10	X
GUSSET, FRONT FENDER APRON, LOWER LH HH	1	\$34.90	\$34.90	X
MEMBER, FRONT APRON TO COWL SIDE, UPPER LH HH	1	\$138.40	\$138.40	X
FRONT APRON TO COWL SIDE, LOWER FRT LH HH	1	\$82.30	\$82.30	X
FRONT WHEEL RIM <i>distorted / key</i>	1	\$1,570.55	\$1,570.55	✓
FRONT WHEEL HUB AND BEARING <i>Distorted</i>	1	\$763.80	\$763.80	✓
FRONT SUSPENSION LOWER ARM (LH) <i>distorted</i>	1	\$637.50	\$637.50	✓
FRONT SHOCK ABSORBER (LH) <i>distorted</i>	1	\$401.80	\$401.80	✓
ABSORBER TOP MOUNTING HH	1	\$196.20	\$196.20	X
FRONT DRIVE SHAFT (LH) HH	1	\$1,764.00	\$1,764.00	X
RACK & PINION ASSY HH	1	\$1,634.90	\$1,634.90	X

BAR, STABILIZER HH	1	\$360.00	\$360.00	X
LINK ASSY, FRONT STABILIZER, LH HH	1	\$199.00	\$199.00	X
KNUCKLE, STEERING, LH <i>distal</i>	1	\$580.80	\$580.80	✓
JOINT ASSY, LOWER BALL, FRONT (LH) <i>distal</i>	1	\$199.98	\$199.98	✓
END SUB-ASSY, TIE ROD, LH HH	1	\$159.30	\$159.30	X
SUB TOTAL			\$18,470.79	
LESS 20% 25%			\$3,694.16	
DISCOUNTED TOTAL			\$14,776.63	
FRONT TYRE (LH) <i>2/</i>	SN 1	\$216.00	\$216.00	X
SUB TOTAL			\$216.00	
Labour Charge				
Panel Beating	1	\$1,600.00	\$1,600.00	600/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	600/-
Wiring Charge	1	\$100.00	\$100.00	30/-
Tuff Kote	1	\$100.00	\$100.00	20/-
Towing Charge	1	\$80.00	\$80.00	HH
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	150/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	HH
TOTAL LABOUR			\$4,150.00	
ESTIMATE TOTAL			\$19,142.63	
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrotauto.com</p>				

31/01/2023 @ 1600hrs

Not Authorized

2/5mm

5 days

Check part prices.

Ryan

2 Kk Auto