



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TP/DS Finalize

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Ong Wenjie 475D Upper Serangoon Crescent #11-557 Singapore 537475 Mobile: 98800223
	Document No. 0	
	Document Date 11/02/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP151R	AEXRKT E1	26/10/2020	SMV8735R	0	22325	69DS/SMV8735R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2B23F3501211400	2NR5458160	60	Raymond Seah L M	07/02/2023 10.09	11/02/2023 9.58		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SLF5481M ACC DATE:20/01/2023 TP INS:INDIA[GRAB] NO OF REPAIR DAYS:04 DATE-IN:07/02/2023 DATE SURVEY:07/02/2023 BY:LKK-MARCUS AUTHORISED ON:26/01/2023 -TP/DS CLAIM				30.00
2	S	BP-SUBLET TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH CASING.	0263			68.00
3	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			198.00
4	S	BP-SUBLET TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.	0742			72.00
5	S	BP-SUBLET TO REPLACE/REPAIR FRONT ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	0742			792.00
6	S	BP-SUBLET TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS.	0742			900.00
7	S	BP-SUBLET PAINT REPAIR - SUPPLY MATERIALS	0742			85.00
8	1	S53112-0D540 GRILLE, RADIATOR, LW	1.00	323.80	30.00	226.66
9	2	S53113-0D020 GRILLE, RADIATOR, LW	1.00	109.30	30.00	76.51
10	3	S52119-0U932 COVER, FR BUMPER, L	1.00	592.80	30.00	414.96

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Ong Wenjie 475D Upper Serangoon Crescent #11-557 Singapore 537475 Mobile: 98800223			
			Document No. 0					
			Document Date 11/02/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	NSP151R	AEXRKT E1	26/10/2020	SMV8735R	0	22325	69DS/SMV8735R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3501211400		2NR5458160	60	Raymond Seah L M	07/02/2023	10.09	11/02/2023 9.58	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
11	4	S52161-0K040 PIECE, RR BUMPER			10.00	4.90	30.00	34.30
12	5	S53111-0D912 GRILLE, RADIATOR, OU			1.00	85.20	30.00	59.64
13	6	S53114-0D020 GRILLE, RADIATOR, IN			1.00	288.00	30.00	201.60
14	7	S90975-T2008 EMBLEM, SYMBOL			1.00	70.10	30.00	49.07
15	8	S81110-0DF01 HEADLAMP ASSY, RH			1.00	1547.20	30.00	1083.04
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 4,290.78	
			Please acknowledge receipt of vehicle		Parts 2,145.78		GST 8.00% 343.26	
					Labour 30.00			
					Sublet 2,115.00			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 4,634.04	

Company Copy

Vehicle Diagnostic Report

2NRFE
070926 km

MR2B23F3501211400

Borneo Motors

Printed By: Default User(1)

11/02/2023 9:52:35 AM

Health Check Results
All Systems(1 of 1)

Enhanced

System	DTC Related Information							RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed				
Engine and ECT	Yes	P1605	X		X			-	30DW1200 A0202000	No
ABS/VSC/TRC								-	F15260D440	No
Steering Angle Sensor									8924GF4010	
EMPS								-	8965B0D140	No
Air Conditioner								-	886500D87001	No
Combination Meter								-	838000UV3002	No
Entry&Start								-	-	No
SRS Airbag								-	8917F0D452	No
Starting Control								-	-	No
Power Source Control								-	-	No

Vehicle Diagnostic Report

2NRFE
070926 km

MR2B23F3501211400

Borneo Motors

Printed By: Default User(1)

11/02/2023 9:53:44 AM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information							RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed				
Engine and ECT								-	30DW1200	No
ABS/VSC/TRC								-	A0202000 F15260D440	No
Steering Angle Sensor								-	8924GF4010	
EMPS								-	8965B0D140	No
Air Conditioner								-	886500D87001	No
Combination Meter								-	838000UV3002	No
Entry&Start								-	-	No
SRS Airbag								-	8917F0D452	No
Starting Control								-	-	No
Power Source Control								-	-	No