

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

LONPAC INSURANCE BHD

300 Beach Road #17-04/07
The Concourse
Singapore 199555
Tel : 6250 - 7388
Fax : 6296 - 2706

Xiao Tony

Quotation

DATE : 26.01.2023
VEH NO : SKX9847H
MODEL : Toyota Altis
D O A : 21.01.2023
YR REF : GBD2291T

Attn : Motor Claim Dept

(Pls arrange vehicle surveyor & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKX9847H (TOYOTA ALTIS)

Item	Description	Qty	Amt
------	-------------	-----	-----

NO LIST ITEMS

1	Front Bumper <i>Distorted</i>	1	589.60 ✓
2	Front Bumper Side Holder - LH & RH <i>Rnd</i>	2	97.80 ✓
3	Front Bumper Reinforcement <i>3 new</i>	1	397.30 +
4	Front Bumper Sponge	1	168.90 +
5	Front Bumper Fog Lamp - LH & RH	2	617.40 +
6	Front Bumper Fog Lamp Cover - LH & RH <i>3 new</i>	2	279.60 +
7	Front Bumper Lower Grille <i>new</i>	1	181.40 +
8	Front Grille <i>cracked</i>	1	564.50 ✓
9	Front Grille Logo <i>new</i>	1	58.90 ✓
10	Front Brace Panel <i>new</i>	1	158.90 +
11	Headlamp - LH & RH <i>cracked</i>	2	5,999.60 ✓
12	Front Support Panel <i>Rear</i>	1	997.20 x
13	Front Fender - LH & RH <i>Dented</i>	2	1,290.20 ✓
14	Front Fender Inner Shield - LH & RH <i>Lit ut</i>	2	365.20 <i>182.60</i>
15	Front Fender VVTI Emblem - LH & RH <i>new</i>	2	116.60 ✓
16	Front Door - LH & RH <i>Dented</i>	2	2,516.80 ✓
17	Front Door Lock - LH & RH <i>3 new</i>	2	749.00 +
18	Front Door Weatherstripe - LH & RH	2	379.20 x
19	Rear Door - RH <i>Rear</i>	1	1,271.60 +
20	Rear Door Lock - RH	1	352.90 +
21	Rear Door Weatherstripe - RH <i>3 new</i>	1	178.40 +
22	Resonator Air Tank <i>ut</i>	1	271.10 ✓
23	Front Wheel Rim - LH & RH <i>ut</i>	2	4,347.00 <i>1800/s20</i>
24	Front Shock Absorber - LH & RH <i>3 LH Best</i>	2	851.60 <i>425.80</i>
25	Front Lower Arm - LH & RH	2	1,087.80 <i>543.90</i>
26	Front Knuckle Arm - LH & RH <i>LH mnd</i>	2	997.20 <i>498.60</i>
27	Front Wheel Hub c/w Bearing - LH & RH <i>LH mnd</i>	2	483.20 <i>241.60</i>
28	Rear Wheel Rim - RH <i>ut</i>	1	2,173.50 <i>900/s20</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SKX9847H (TOYOTA ALTIS)

13397.60 S.N: 2700
10048.20 Less 25%

\$	27,542.40
	(6,885.60)
\$	20,656.80

S/NETT ITEMS

1	Front Bumper Clips <i>3 new</i>	1 set	30.00 ✓
2	Front Grille Clips	1 set	20.00 ✓
3	Front Fender Inner Shield Clips - LH & RH <i>lit new</i>	2 sets	60.00 30
4	Front Door Black Tape - LH & RH <i>new</i>	2	120.00 ✓
5	Rear Door Black Tape - RH <i>new</i>	1	60.00 +
6	Front Tyre - LH & RH <i>new</i>	2	500.00 +
7	Rear Tyre - RH <i>new</i>	1	250.00 +
Total Parts			\$ 21,696.80

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$	2,000.00 1200
2	To putty & spray up paint works	\$	2,000.00 1700
3	To check wiring system	\$	100.00 30
4	To spray tuff coat	\$	150.00 100
5	To remove condenser & top-up aircon gas	\$	120.00 X
6	To remove radiator & top-up coolant	\$	120.00 +
7	To transfer front LH & RH door fittings	\$	300.00 160
8	To transfer rear RH door fittings	\$	150.00 X
9	To remove front LH & RH undercarriages	\$	650.00 220
10	To perform wheel alignment	\$	150.00 80
11	Towing Fees	\$	60.00 ✓
Total Labour			\$ 5,800.00

Grand Total**\$ 27,496.80****GST Will be reflected in the final bills****NOTE : -**

RE : ESTIMATE FOR ACCIDENT REPAIR SKX9847H (TOYOTA ALTIS)

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 1649820

h/s: 13.2K

10 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: