



Section A - Accident Details

Registration Number	SHB5815C
Case Reference Number	TAX/01/23/2046
Registration Date	1/Dec/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	GIOK LOO BENG
Type of Accident	Side Swipe
Accident Date and Time	20/Jan/2023 1:45 PM
Accident Reported Date and Time	20/Jan/2023 2:30 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117497
Special Instruction to ARC, if any	RIGHT FRONT PORTION / TOS TILL 26/01/2023
Prepared Date and Time	26/Jan/2023 3:23 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,116.00	\$500.00
Total Spare Part Cost	\$3,663.17	\$839.86
Total Other Cost	\$500.00	\$140.00
TOTAL COST	\$5,955.17	\$1,779.86 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / China Taiping
ARC / Surveyor Sign Off Date	27/01/2023 5:23 PM	27/01/2023 3:07 PM
Signature		
Remarks	PART BY PART / Before paint photo , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Taufikh HP/ 97495749 , Email :mdfikh@gmail.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0182	Invoice Number	
Quotation Date	16.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$300.00 ✓
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$100.00 ✓
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$500.00	\$140.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		8791547070A1	COVER, OUTER MIRROR, RH	0.00	\$117.80	0.00	\$0.00	Replace	Not Given
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Not Given
		4261147450	WHEEL, DISC FRONT	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair
		5387547070	LINER, FR FENDER, RH	0.00	\$223.50	0.00	\$0.00	Replace	Check
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace
		5380147080	FENDER SUB-ASSY, FR, RH	1.00	\$1,060.70	25.00	\$795.53	Replace	Replace
		5211547050	SUPPORT, FR BUMPER RH	0.00	\$86.20	0.00	\$0.00	Replace	Check
		5211947962	COVER, FR BUMPER	1.00	\$560.30	100.00	\$0.00	Replace	Repair
Total					\$4,870.80		\$839.86		

X
X NN
X
R
X NN
✓ NEC
✓ BT
X NN
R

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

839.86
+ 300.00
+ 640.00
1,779.86