



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S	LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/06 THE CONCOURSE, SINGAPORE 199555
Insured	JURONG ISLAND BUS TRANSPORT SERVICES
Policy	GA567962

ESTIMATE BILL

GST Reg. No: 199800107D

Date: 30/1/2023

Our Case Ref.

Accident Date 10/8/2020

Damaged Vehicle No: PC9013Z

S/no	Description	QTY	Price	Remark
<u>Replaced Parts</u>				
1	LUGGAGE COMPARTMENT LOCK	1 PC	\$ 268.00	\$ 268.00
2	ARTWORK		\$1,000.00	\$ 1,000.00
<u>Labour Charges</u>				
1	LABOUR TO REMOVE, REPAIR AND REINSTALL LUGGAGE COMPARTMENT PANEL.	640	\$1,920.00	\$ 1,920.00
2	LABOUR TO RESPRAY LUGGAGE COMPARTMENT PANEL AND SIDE PANEL RH.	640	\$3,000.00	\$ 3,000.00

TOTAL \$ 6,188.00

Tanjiu 9749544
wp, 30/1/23 21145
Resurvey after repair
tanjiu@lkharts.com.
4days

LKK Auto Consultants Notice notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: