

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 01.02.2023MODEL: Hyundai i40VEHICLE NO.: SHA5276MINSURANCE: INCOME (45)MVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Front Bumper	1		\$ 1,052.20	/CRA
	Front Bumper Clips	10	\$ 2.20	\$ 22.00	/NEC
	Front Bumper Upper Brkt RH	1		\$ 22.40	?
	Front Wheel Cap RH	1		\$ 217.20	/CRA
	Front Fender RH	1		\$ 663.00	/DD
	HeadLamp RH	1		\$ 1,388.00	/SR
	Front Door RH	1		\$ 2,707.70	/DD
	Front Door Hinge Upper	1		\$ 113.60	?
	Front Door Hinge Lower	1		\$ 113.60	?
	Front Wheel Apron RH	1		\$ 637.00	?
	Front Wheel Rim RH	1		\$ 325.30	/SR
	Front Lower Arm RH	1		\$ 595.90	?
	Front Shock Absorber RH	1		\$ 684.40	?
	Rocker Panel Garnish RH	1		\$ 732.80	/DEF
	SUB TOTAL			\$ 9,275.10	
	LESS 20%			\$ 1,855.02	
	DISCOUNTED TOTAL			\$ 7,420.08	
	Front Door ComfortDelGro RH	1		\$ 75.00	/NEC
	LESS 10%			\$ 7.50	
	S/NETT TOTAL			\$ 67.50	
	Front Fender Adv.Sticker RH	1		\$ 100.00	NETT /NEC
	Front Door Adv.Sticker RH	1		\$ 100.00	NETT /NEC
	SPARE PARTS TOTAL			\$ 7,428.83	
	Labour Charge				
	Panel Beating			\$ 1,200.00	1,200
	Spray Painting Charge			\$ 1,200.00	900
	Check Lightings			\$ 60.00	30
	Tuff Kote			\$ 100.00	60
	R/I Front Suspension RH			\$ 200.00	?
	Wheel Alignment			\$ 120.00	?
	Towing Fee			-	
	TOTAL LABOUR			\$ 2,880.00	
	ESTIMATE TOTAL			\$ 10,308.83	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHECK ITEM PHOTO

AFTER REPAIR PHOTO

REQUEST BOOK VALUE