## COMFORTDELGRO ENGINEERING PTE LTD

## **REPAIR ESTIMATE\***

**VEHICLE NO** 

SH6609M

REG. 07.11.2019

31.01.2023

CHIANG/INCOME

MAKE MODEL

**IONIQ G3** 

Qty	Parts Description/ Labour	Type		Amount	
1	REAR BUMPER			\$459.40	XR
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80	\$111.60	? x 9
10	REAR BUMPER CLIPS		\$2.20	\$22.00	5 X2
1	REAR BUMPER CENTRE MOULDING			\$451.25	/CR
1	REAR BUMPER REINFORCEMENT			7331.00	? 73
1	REAR BUMPER REFLECTOR LH			\$41.50	?X5
1	REAR REINFORCEMEN STAY LH/RH		\$138.10	\$276.20	
2	REAR NUMBER PLATE LAMP LH/RH			\$85.30	XSV
1	TOWING COVER			\$98.80	XSV
2	REAR FOG LAMP			\$201.50	7, X:
	SUB TOTAL			\$2,142.35	
	20.00%			\$428.47	
	DISCOUNTED TOTAL			\$1,713.88	
1	REAR NUMBER PLATE W/HOLDER			\$55.00	10
	REAR REVERSE SENSOR			\$180.00	XS
				\$211.50	
L	abour Charge				
F	Panel Beating			\$550.00	33
S	Spray Painting Charge			\$300.00	
Τ	ruff Coating			\$60.00	14
c	Check Wiring and Lighting			\$60.00	
	emove/refix Reverse sensor			\$60.00	1
	TOTAL LABOUR			\$1,030.00	
-	ESTIMATE TOTAL			\$2,955.38	
-	LOTIMATE TOTAL			<u>32,333.30</u>	4
F	nis is an initial estimate based on a visual inspection of the				1
be	prepared after the vehicle is surveyed by a motor Surveyo	or appointe	ed by the insurance cor	npany.	

NAZ UKK

112/2023 1610

LIS

2 DAYS

CHECK ITEM PHOTO

APTEL REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date.