

**ComfortDelGro Engineering Pte Ltd**  
**59 Loyang Drive Singapore 508969**

Our Job Ref No : **305544244**

Date : 08.02.2023

## FINALIZATION FORM

To : \_\_\_\_\_ LKK

**Fax :**

Attn : \_\_\_\_\_ **NAZ**

Vehicle Reg No. : SH6609M

**31.01.2023**

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

**Z      The repair job shall bill to:** **INCOME** **SND5722E**

**2. The finalized amount shall be:**

**(a) Spare Parts after List discount**

**(b) Labour Charges**

**Total for Part-By-Part Repair Cost**

(c.) **Lumpsum Repair (if applicable)**

**Total for Lumpsum repair cost after Less:**

**Final Lumpsum Repair cost**

**\$850.00**

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

**We confirm the estimates and finalized amount**

Signature : \_\_\_\_\_

Signature: 

Name : CHIANG

Name : NAZ LKIC

**Tel : 62148314**

Date : 20/02/2023

**Fax : 65468156**

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$26.75/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SH6609M

31.01.2023

MAKE REG. 07.11.2019

CHIANG/INCOME

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount	
1	REAR BUMPER		\$459.40	XR
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80	? XSVL
10	REAR BUMPER CLIPS		\$2.20	? XSVL
1	REAR BUMPER CENTRE MOULDING		\$451.25	✓ CRA
1	REAR BUMPER REINFORCEMENT		\$394.80	? XSVL
1	REAR BUMPER REFLECTOR LH		\$41.50	? XSVL
1	REAR REINFORCEMENT STAY LH/RH		\$138.10	? XSVL
2	REAR NUMBER PLATE LAMP LH/RH		\$85.30	XSVL
1	TOWING COVER		\$98.80	XSVL
2	REAR FOG LAMP		\$201.50	? XSVL
	<b>SUB TOTAL</b>		<b>\$2,142.35</b>	
	<b>20.00%</b>		<b>\$428.47</b>	
	<b>DISCOUNTED TOTAL</b>		<b>\$1,713.88</b>	
1	REAR NUMBER PLATE W/HOLDER		\$55.00	✓ CRA
1	REAR REVERSE SENSOR		\$180.00	XSVL
			<b>\$211.50</b>	
	<b>Labour Charge</b>			
	Panel Beating		\$550.00	350
	Spray Painting Charge		\$300.00	250
	Tuff Coating		\$60.00	40
	Check Wiring and Lighting		\$60.00	XNN
	Remove/refix Reverse sensor		\$60.00	30
	<b>TOTAL LABOUR</b>		<b>\$1,030.00</b>	
	<b>ESTIMATE TOTAL</b>		<b>\$2,955.38</b>	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NA2 LKX

11/2/2023 1610

L/S

2 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: